

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110329/KMA3Q2
Date: 18/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MPC0006701_01
Claimant Vehicle No : SCG9885G Insured Vehicle No : SJJ9565G
Date of Loss: 13/11/2024 Nature of Claim: TP Claim No: MPC2024D0013523

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SCG9885G
Make & Model: NISSAN SYLPHY, 1.6 CVT (A) Engine No: HR16933464C
Reg. Date: 17/01/2019 (Man. Year: 2018) Chassis No: MNTBBAB17Z0033299
Colour: Metallic Silver Odometer: 45038 km
Engine Capacity: 1598 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16 Rear Tyre Size: 195/60 R16
Front Left Side: Yokohama 8 mm Rear Left Side: Yokohama 9 mm
Front Right Side: Yokohama 8 mm Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,816.80	4,621.45	3,195.35	40.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,420.00	2,100.00	320.00	13.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,236.80	6,721.45	3,515.35	34.34
Approved Total (Overridden) (S\$)		5,350.00		
Nett Amount (S\$)	10,236.80	5,350.00	4,886.80	47.74
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		6,077.25		
Global Sum Settlement (S\$)		6,000.00		

INSPECTION

Date of Assignment: 18/11/2024
Date Inspected: 18/11/2024 Inspected At: Eng Heng Automobil Trading Co (HQ)
Blk 10 #01-01 Ang Mo Kio Part 2A AutoPoint
Singapore 568047
Estimated Period of Repair: 7.0 days

Adjuster: KENNETH KONG Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Jan 2025)
Parts:	143	NISSAN SYLPHY 1.6 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCG9885G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Bent	814.30 F	*814.30 FL
2	1		*REAR BOOT RUBBER (50%)	Distorted / Dented	94.90 FS	*47.45 FS
3	1		*REAR BOOT LOCK	Repair	78.90 F	*- FL
4	1		*REAR STRIKER	Repair	70.80 F	*- FL
5	1		*REAR BUMPER	Cracked	773.00 F	*632.90 FL
6	1		*REAR BUMPER SIDE RETAINER RIGHT /LEFT	N/S Distorted	159.80 F	*79.90 FL
7	1		*REAR BUMPER REINFORCEMENT SPONGE	Cracked	165.00 F	*165.00 FL
8	10		*REAR BUMPER CLIPS	Necessary	45.00 F	*45.00 FL
9	2		*REAR STOPPER (END PANEL) RIGHT N LEFT	Serviceable	124.20 F	*- FL
10	1		*REAR BUMPER REFLECTOR -LEFT	Missing	68.90 F	*68.90 FL
11	1		*REAR LEFT TAIL LAMP	Mtg Cracked	185.90 F	*185.90 FL
12	1		*REAR RIGHT TAIL LAMP	Mtg Cracked	185.90 F	*185.90 FL
13	2		*REAR HEADLAMP CLIPS	Necessary	17.00 F	*17.00 FL
14	1		*REAR END PANEL	Bent	475.90 F	*475.90 FL
15	1		*REAR END PANEL GARNISH	Buckled	106.00 F	*106.00 FL
16	1		*SET REAR NUMBER PLATE	Dented	60.00 FS	*45.00 FS
17	1		*REAR LEFT STOPPER	Missing	62.10 F	*62.10 FL
18	1		*REAR LEFT FENDER	Buckled	1,717.70 F	*1,685.40 FL
19	1		*REAR RIGHT FENDER	Repair	1,717.70 F	*- FL
20	1		*SET REVERSE SENSOR	Torn	380.00 FS	*200.00 FS
21	1		*SPARE TYRE COMPARTMENT COVER	Serviceable	228.00 F	*- FL
22	1		*SPARE TYRE COMPARTMENT TOOLS COVER	Deformed	285.80 F	*285.80 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,816.80	5,102.45
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	481.00
Total Parts (\$\$)	7,816.80	4,621.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO CHARGE TO REMOVE DAMAGED PARTS AND FIT NEW PARTS ,PANEL BEATING REAR SPARE TYRE COMPARTMENT TO FIT AND REALIGN	New	1,100.00	1,000.00
2	TO RESPRAY PAINT REAR BUMPER, REAR END PANEL,REAR BOOT LID ,REAR BUMPER AND SPARE TYRE COMPARTMENT	New	1,200.00	1,100.00
3	COMPUTERIZED 4 WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (\$\$)			2,420.00	2,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >