9/3/24, 3:49 PM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24060277/UPA3Q2

03/09/2024 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_04

Claimant Vehicle SLG6646T Insured Vehicle No: GBJ8293S

No:

Date of Loss: 25/06/2024 Nature of Claim: TP Claim No: MFL2024D0008154

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLG6646T**

Make & Model: HONDA STREAM, 1.8 L (A) Engine No: R18A12805685 Reg. Date: 13/12/2008 (Man. Year: 2008) Chassis No: JHMRN68408S205688

Colour: Black Odometer: 393048 km

Engine Capacity: 1799 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Yes Engine Modification: No Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15 Front Left Side: Rear Left Side: Yokohama 6 mm Yokohama 6 mm Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		8,722.32	2,421.20	6,301.12	72.24
Miscellaneous Items		0.00	0.00	0.00	
Labour		3,580.00	1,740.00	1,840.00	51.40
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	12,302.32	4,161.20	8,141.12	66.18
	Approved Total (Overridden) (S\$)		3,300.00		
	(S\$)	12,302.32	3,300.00	9,002.32	73.18
	+ GST 9.00/9.00% (S\$)	1,107.21	297.00	810.21	73.18
	Nett Amount (S\$)	13,409.53	3,597.00	9,812.53	73.18
	+ Loss of Use (4.0 x S\$	880.00/day) (S\$)	320.00		
	+ Doc/\$	Search Fee (S\$)	27.25		
	Ne	ett Liability (S\$)	3,944.25		

INSPECTION

Date of Assignment: 27/06/2024

Carsmith Private Limited (HQ) Date Inspected: 27/06/2024 Inspected At:

8 Kaki Bukit Ave 4, #04-35 Premier

Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: **CHEW HSIAO TONG** NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

9/3/24, 3:49 PM Adjuster Report

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 17 Jul 2024)

Parts: M1-MPV HONDA STREAM 1.8 L (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLG6646T)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented / Bent	1,423.00 FL	*953.00 FL
2	1		*TAILGATE INNER TRIM BOARD	Serviceable	390.00 FL	*- FL
3	1		*TAILGATE WEATHERSTRIP	Twisted	197.00 FL	*197.00 FL
4	1		*TAILGATE INNER LOCK	Damaged	286.00 FL	*286.00 FL
5	1		*TAILGATE DAMPER LH	Not Necessary	231.00 FL	*- FL
6	1		*TAILGATE DAMPER RH	Not Necessary	231.00 FL	*- FL
7	1		*TAILGATE LOGO	Not Necessary	98.00 FL	*- FL
8	1		*TAILGATE EMBLEM STREAM	Necessary	95.00 FL	*48.00 FL
9	1		*TAILGATE OUTER GARNISH	Not Necessary	393.10 FL	*- FL
10	1		*TAILGATE INNER HANDLE GARNISH	Not Necessary	78.00 FL	*- FL
11	1		*TAILGATE WIPER MOTOR	Not Necessary	485.00 FL	*- FL
12	1		*TAILLAMP LH	Not Necessary	690.60 FL	*- FL
13	1		*TAILLAMP PANEL LH	Not Necessary	204.60 FL	*- FL
14	1		*TAILLAMP RH	Not Necessary	690.60 FL	*- FL
15	1		*TAILLAMP PANEL RH	Not Necessary	204.60 FL	*- FL
16	1		*REAR END PANEL	Bent	910.00 FL	*452.00 FL
17	1		*REAR END PANEL TOP GARNISH	Not Necessary	187.00 FL	*- FL
18	1		*REAR EXHAUST COVER	Not Necessary	195.00 FL	*- FL
19	1		*REAR BUMPER	Dented	1,530.00 FL	*698.00 FL
20	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	120.20 FL	*- FL
21	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	120.20 FL	*- FL
22	1		*REAR BUMPER BRACKET LH	Not Necessary	98.00 FL	*- FL
23	1		*REAR BUMPER BRACKET RH	Not Necessary	98.00 FL	*- FL
24	2		*REAR BUMPER SPONGE	No such part	196.00 FL	*- FL
25	1		*REAR BUMPER TOW COVER	Missing	48.00 FL	*30.00 FL
26	1		*REAR BUMPER REFLECTOR GARNISH LH	No such part	169.00 FL	*- FL
27	1		*REAR BUMPER REFLECTOR GARNISH RH	No such part	169.00 FL	*- FL
28	1		*REAR BUMPER REFLECTOR LH	No such part	145.00 FL	*- FL
29	1		*REAR BUMPER REFLECTOR RH	No such part	145.00 FL	*- FL
30	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*40.00 FS
31	1		*TAILGATE INNER SEAL	Necessary	50.00 FS	*20.00 FS
32	1		*TAILGATE SEALANT	Not Necessary	100.00 FS	*-FS
33	1		*SET TAILGATE TRIMBOARD CLIPS	Not Necessary	50.00 FS	*- FS
34	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*-FS
35	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
36	1		*REAR END PANEL SEALANT	Not Necessary	80.00 FS	*-FS
37	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*SET REVERSE SENSOR W MODULE	Malfunction	300.00 FS	*200.00 FS
	nchise	nart S=SncN	Nett. L=ListItemDisc.			

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) - List Item Discount on L Items 20.00/20.00% (S\$)	10,687.90 1,965.58	2,954.00 532.80	
Total Parts (S\$)	8,722.32	2,421.20	

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	100.00	20.00
2	TO REMOVE AND REFIT REAR TAILGATE GLASS TO FACILITATE THE REPAIR	New	200.00	120.00
3	TO REMOVE AND REFIT TAILGATE COMPONENT TO REPLACE TAILGATE ,CHECK AND RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE	New	100.00	60.00
4	TO REMOVE AND REFIT INTERIOR UPHOLSTERY TO FACILITATE THE REPAIR	. New	200.00	60.00
5	TO MEASURE ,DRILLS HOLES ON REPLACED REAR BUMPER,POSITION AND INSTALL REVERSE SENSOR CHECK AND TEST ON THE DISTANCE AND FUNCTIONS	New	80.00	30.00
6	PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	New	1,400.00	600.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,400.00	800.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	50.00
	Gross Labour	r Cost (S\$)	3,580.00	1,740.00
	Report was unsubmitted during this p	print-out.		

< END OF ESTIMATES >