



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2500405

16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING
SINGAPORE 048581
ATTN:JOANNE YONG

INV Date 16/01/2025
Reference CD/FCI24110334/Uua3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SLT 3936H
Insured Veh. SHB 2978K
Claim No. D24009279MFCT/CCPL/JY/TPD-2
Policy No. D-24101860MFCT
Accident Date 18/10/2024
Inspection Date 24/10/2024

Description	Total
Third Party Express Settlement	300.00
Subtotal	300.00
GST (9%)	27.00
Grand Total	327.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDING SINGAPORE 048581		Ref: CD/FCI24110334/Uua3q2 Date: 16/01/2025 Code: FCI2		
1. Policy Particulars :- DIRECT SETTLEMENT				
Insured Veh.	SHB 2978K	Veh. Inspected	SLT 3936H	
Policy No.	D-24101860MFCT	Coverage	0	
Claim No.	D24009279MFCT/CCPL/JY/TPD-2	Excess	\$0.00	
Assign From	JOANNE YONG	Assign Date	23/10/2024	
2. Vehicle Details				
Make & Model	SUBARU XV 1.6I-S AWD CVT	C.C	1600	
Engine No.	FB16YB40569	Year of Reg.	27/10/2017	
Chassis No.	JF1GT3KC5JG022995	Colour	SILVER	
Odometer	182728 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	225/60R17	YOKOHAMA	7	
L/H Front Tyre	225/60R17	YOKOHAMA	7	
R/H Rear Tyre	225/60R17	YOKOHAMA	7	
L/H Rear Tyre	225/60R17	YOKOHAMA	7	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/10/2024	Inspection Date	24/10/2024	
Survey held at	FOCUS AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #02-50 KAKI BUKIT @ AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLT 3936H

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	TORN	\$534.50	\$534.50
1	REAR BUMPER TOP PROTECTOR	DEFORMED / TWISTED	\$981.00	\$480.00
1	REAR BUMPER TOWING COVER	TORN	\$22.00	\$22.00
1	REAR BUMPER REINFORCEMENT	BENT	\$250.30	\$250.30
1	SET REAR BUMPER CLIPS	NECESSARY	\$42.00	\$42.00
	LESS 10.00 / 20.00% DISCOUNT		(\$182.98)	(\$265.76)
			\$1,646.82	\$1,063.04

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER SENSOR (SN)	SERVICEABLE	\$300.00	\$0.00
1	SUNDRIES (SN)	NOT NECESSARY	\$30.00	\$0.00
			\$330.00	\$0.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING		\$650.00	\$280.00
	CHECK WIRING		\$60.00	\$20.00
	SPRAY PAINT		\$500.00	\$400.00
			\$1,210.00	\$700.00

GRAND TOTAL		\$3,186.82	\$1,763.04
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)		\$1,400.00
Report Ref No: CD/FCI24110334/Uua3q2			

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 1 of 11)

PHOTOGRAPHS FOR VEHICLE NO. : SLT 3936H



PHOTOGRAPHS FOR VEHICLE NO. : SLT 3936H



PHOTOGRAPHS FOR VEHICLE NO. : SLT 3936H



PHOTOGRAPHS FOR VEHICLE NO. : SLT 3936H



PHOTOGRAPHS FOR VEHICLE NO. : SLT 3936H





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 6 of 11)

PHOTOGRAPHS FOR VEHICLE NO. : SLT 3936H



PHOTOGRAPHS FOR VEHICLE NO. : SLT 3936H



PHOTOGRAPHS FOR VEHICLE NO. : SLT 3936H



PHOTOGRAPHS FOR VEHICLE NO. : SLT 3936H



PHOTOGRAPHS FOR VEHICLE NO. : SLT 3936H



PHOTOGRAPHS FOR VEHICLE NO. : SLT 3936H



PHOTOGRAPHS FOR VEHICLE NO. : SLT 3936H



PHOTOGRAPHS FOR VEHICLE NO. : SLT 3936H



PHOTOGRAPHS FOR VEHICLE NO. : SLT 3936H



PHOTOGRAPHS FOR VEHICLE NO. : SLT 3936H



PHOTOGRAPHS FOR VEHICLE NO. : SLT 3936H





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SLT 3936H





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SLT 3936H

