## **ELITE AUTO RESTORATION PTE LTD**

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg: 202424577D

Vehicle Number:

**SKW 8228G** 

Date:

18.11.2024

Vehicle Model:

**TESLA 3 MODEL** 

Chassis: LRW3F7FA3MC385236

**Accident Date:** 

14.11.2024

TP Ins.

LONPAC

Original Reg Date: 29.12.2021

## **ESTIMATE**

1	1 pc	Front Bumper Delad	725.30	1
2	1 pc	Front Bumper Side Retainer LH	95.80	2 34
3	1 pc	Front Bumper Fog Lamp LH	298.50	X
4	1 pc	Front Bumper ultrasonic sensor LH N ~~	386.20	4
5	1 pc	Front Fender LH Devtid	536.80	1
6	1 pc	Front Fender outer garnish LH	205.60	+ ,
7	1 pc	Front fender inner shield LH Form	135.80	2
8	1 pc	Headlamp LH At	1,425.30	/
9	1 pc	Headlamps Bottom Retainer ** W	92.70	1
10	1 pc	Front door Lh Nee M	1,023.50	*/
11	1 pc	Front Rim LH	1,135.80	
12	1 pc	Front Knuckle arm	658.90	+
13	1 pc	Front absorber LH	569.20	+
14	1 pc	Front lower arm LH	625.30	2
15	1 pc	Front wheel hub bearing LH 2	458.90	+
16	1 pc	Front trackarm LH	598.20	7
17	1 pc	Front trailing arm LH	498.00	1

\$3,993.00

SUBTOTAL

9,469.80

\$3,593.70

		Special Nett	
1	1 set	Front bumper clips	30.00
2	1 pc	Front tyre / t	450.00 23
3	1 set	Front fender inner shield clips ~~	30.00
5	1 set	Headlamp clips APP M	30.00

subtotal

540.00

310

Labour charge

x \*\* 4

Panel Beating		1,200.00	500
Spray painting		1,200.00	400
Check Wiring on front headlamps		120,00	30
To remove / install front sensor and settling		100,00	50
Anti rust		180.00	X
Remove and install front undercarriage.		350.00	X
To perform computerize wheel alignment		120.00	80
	subtotal	\$ 4,350.00	

1060

**Total** 14,359.80

Adrian Ly 2 18/1/27. 04 Days. total: \$4,963.70 1/5: 3.51C

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurreyed and is subject to final approval from Insurance Company

Acknowledged by Repairer