



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBL 7898T

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE GARNISH	CRACKED	\$250.00	\$126.00
1	REAR NUMBER PLATE GARNISH BRACKET	BUCKLED	\$80.00	\$53.00
1	REAR NUMBER PLATE LAMP	BROKEN	\$60.00	\$60.00
1	REAR SIGNAL LAMP	CUT	\$45.00	\$45.00
1	REAR BOX BRACKET	TO REPAIR SEE LABOUR	\$250.00	\$0.00
1	REAR BOX SIDE BRACKET	BENT	\$200.00	\$200.00
1	REAR SEAT LOCK	TO REPAIR SEE LABOUR	\$140.00	\$0.00
1	REAR SWING ARM	BENT	\$850.00	\$420.00
1	REAR SWING ARM BUSHING	NECESSARY	\$120.00	\$21.60
1	REAR RIM	SERVICEABLE	\$300.00	\$0.00
1	REAR CHAIN	SERVICEABLE	\$180.00	\$0.00
1	REAR SPROCKET	SERVICEABLE	\$150.00	\$0.00
1	REAR CHAIN COVER	SERVICEABLE	\$90.00	\$0.00
1	REAR FOOT REST	SERVICEABLE	\$40.00	\$0.00
1	REAR FOOT REST BRACKET	TO REPAIR SEE LABOUR	\$90.00	\$0.00
1	MAIN STAND ARM	TO REPAIR SEE LABOUR	\$180.00	\$0.00
1	FRONT FOOT REST	DENTED	\$40.00	\$40.00
1	GEAR LIVER PEDAL	DISTORTED	\$45.00	\$45.00
1	ENGINE MAGNET COVER	SERVICEABLE	\$150.00	\$0.00
1	ENGINE MAGNET COVER GASKET	NOT NECESSARY	\$25.00	\$0.00
1	SET TAIL FAIRING	SERVICEABLE	\$200.00	\$0.00
1	SET SIDE FAIRING	SERVICEABLE	\$250.00	\$0.00
1	SET FRONT FAIRING	SERVICEABLE	\$200.00	\$0.00
1	DASH FAIRING	SERVICEABLE	\$150.00	\$0.00
1	DASH INNER FAIRING	SERVICEABLE	\$150.00	\$0.00
1	FRONT BOX	SERVICEABLE	\$350.00	\$0.00
1	FRONT BOX BRACKET	TO REPAIR SEE LABOUR	\$80.00	\$0.00
1	MIRROR LH	DENTED	\$60.00	\$60.00
1	HEAD LAMP COWLING	SERVICEABLE	\$180.00	\$0.00
1	CLUTCH LEVER	SERVICEABLE	\$30.00	\$0.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	STEERING CONE	SERVICEABLE	\$150.00	\$0.00
1	HANDLE BAR	BENT	\$150.00	\$150.00
1	HANDLE GRIP	CUT	\$45.00	\$45.00
1	HANDLE BALANCER	NO SUCH PARTS	\$60.00	\$0.00
2	FRONT SIGNAL LAMP @ \$120	SERVICEABLE	\$240.00	\$0.00
2	FRONT POLIT LAMP @ \$100	SERVICEABLE	\$200.00	\$0.00
1	FRONT FENDER	SERVICEABLE	\$160.00	\$0.00
1	FRONT FENDER	SERVICEABLE	\$35.00	\$0.00
1	RADIATOR	SERVICEABLE	\$250.00	\$0.00
2	FRONT FORK @ \$100	SERVICEABLE	\$200.00	\$0.00
2	FRONT FORK BRACKET @ \$100	SERVICEABLE	\$200.00	\$0.00
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$126.56)
			\$6,625.00	\$1,139.04

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BOX (SN)	DENTED/CUT	\$450.00	\$220.00
1	REAR NUMBER PLATE (SN)	MISSING	\$20.00	\$15.00
1	ENGINE OIL (SN)	NOT NECESSARY	\$60.00	\$0.00
1	REAR TYRES (SN)	SERVICEABLE	\$150.00	\$0.00
1	BODY STICKER (SN)	NOT NECESSARY	\$200.00	\$0.00
1	FORK OIL (SN)	NOT NECESSARY	\$60.00	\$0.00
1	FORK SEAL (SN)	NOT NECESSARY	\$60.00	\$0.00
1	O.B.U (SN)	DENTED	\$380.00	\$240.50
			\$1,380.00	\$475.50

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS. INCLUSIVE OF THE REPAIR OF REAR BOX BRACKET, REAR SEAT LOCK, REAR FOOT REST BRACKET, MAIN STAND ARM AND FRONT BOX BRACKET		\$1,000.00	\$180.00
	TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA	NOT NECESSARY	\$600.00	\$0.00
	TO SUPPLY LABOUR TO STRAIGHTEN BODY		\$600.00	\$100.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	NOT NECESSARY	\$200.00	\$10.00
	TO SUPPLY LABOUR TO ALIGN FRONT BAR		\$300.00	\$0.00
			\$2,700.00	\$290.00
GRAND TOTAL			\$10,705.00	\$1,904.54
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,500.00
Report Ref No: CS/LIP24110339/Kvh3m4				

MARKET VALUE: \$5,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$1,730.00=NETT VALUE: \$3,270.00

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.