

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110340/UPA3Q2
Date: 05/05/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D20MCV0002262_04
Claimant Vehicle No : SNF2020G Insured Vehicle No : GBH4050M
Date of Loss: 15/11/2024 Nature of Claim: TP Claim No: MCV2024D0013680

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SNF2020G
Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A) Engine No: 2ZR8190067
Reg. Date: 23/04/2018 (Man. Year: 2017) Chassis No: ZYX102073531
Colour: Grey Odometer: 190187 km
Engine Capacity: 1797 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-----------------------------------|------------|------------|------------|--------|
| Parts | 6,755.42 | 2,631.30 | 4,124.12 | 61.05 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,210.00 | 800.00 | 2,410.00 | 75.08 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 9,965.42 | 3,431.30 | 6,534.12 | 65.57 |
| Approved Total (Overridden) (S\$) | | 2,700.00 | | |
| Nett Amount (S\$) | 9,965.42 | 2,700.00 | 7,265.42 | 72.91 |
| Global Sum Settlement (S\$) | | 0.00 | | |

INSPECTION

Date of Assignment: 18/11/2024
Date Inspected: 18/11/2024 Inspected At: V.z Automotive Pte Ltd (HQ)
1 Kaki Bukit Avenue 6 #02-02
Singapore 417883
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

| | | |
|---------------|--|--|
| Reference | | |
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 02 Jan 2025) |
| Parts: | M1-SUV | TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SNF2020G) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|-----------------------------------|---------------|-------------|--------------|
| 1 | 1 | | *FRONT BUMPER | Cut / Torn | 1,986.70 FL | *585.00 FL |
| 2 | 1 | | *FRONT BUMPER REINFORCEMENT | Not Necessary | 625.00 FL | *- FL |
| 3 | 1 | | *FRONT BUMPER RETAINER RH | Not Necessary | 110.20 FL | *- FL |
| 4 | 1 | | *FRONT BUMPER BRACKET RH | Not Necessary | 98.70 FL | *- FL |
| 5 | 1 | | *FRONT BUMPER FOG LAMP COVER RH | Not Necessary | 225.00 FL | *- FL |
| 6 | 1 | | *FRONT BUMPER LOWER GRILLE | Not Necessary | 585.00 FL | *- FL |
| 7 | 1 | | *FRONT PANEL TOP GARNISH | Not Necessary | 475.00 FL | *- FL |
| 8 | 1 | | *FRONT HEADLAMP RH | Cracked | 2,586.70 FL | *2,586.70 FL |
| 9 | 1 | | *FRONT FENDER RH | Repair | 786.90 FL | *- FL |
| 10 | 1 | | *FRONT FENDER OUTER PROTECTOR RH | Cut | 296.70 FL | *296.70 FL |
| 11 | 1 | | *FRONT FENDER TRIM | Not Necessary | 258.00 FL | *- FL |
| 12 | 1 | | *SET FRONT BUMPER CLIP | Necessary | 50.00 FS | *30.00 FS |
| 13 | 1 | | *SET FRONT PANEL TOP GARNISH CLIP | Not Necessary | 50.00 FS | *- FS |
| 14 | 1 | | *SET FRONT PARKING SENSOR | Not Necessary | 480.00 FS | *- FS |
| 15 | 1 | | *SET TAILGATE INNER TRIM CLIP | Not Necessary | 50.00 FS | *- FS |
| 16 | 1 | | *JOINT SEALANT | Not Necessary | 100.00 FS | *- FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|----------|----------|
| Sub Total (S\$) | 8,763.90 | 3,498.40 |
| - List Item Discount on L Items 25.00/25.00% (S\$) | 2,008.48 | 867.10 |
| Total Parts (S\$) | 6,755.42 | 2,631.30 |

| |
|---|
| Report was unsubmitted during this print-out. |
|---|

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------------------|--|----------|-----------------|---------------|
| Labour Items | | | | |
| 1 | CHECK ALL WIRING AND LIGHTING SYSTEM | New | 240.00 | 20.00 |
| 2 | REMOVE AND RENEW PARKING REVERSE SENSOR | New | 120.00 | 0.00 |
| 3 | REMOVE AND REFIT FRONT LINING ,TRIM AND GARNISH | New | 300.00 | 0.00 |
| 4 | PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS | New | 1,200.00 | 280.00 |
| 5 | SPRAY PAINTING ON AFFECTED AREAS | New | 1,200.00 | 500.00 |
| 6 | APPLY ANTI RUST ON AFFECTED AREAS | New | 150.00 | 0.00 |
| Gross Labour Cost (\$\$) | | | 3,210.00 | 800.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >