

Insurer Reference: SJW3078S
 Repairer Reference: CM134/SJW3078S
 Date calculated: 31/12/2024 10:26 AM

Full Report
 Registration: SJW3078S
 Printed: 31/12/2024 10:26 AM

Code	Description	Part Number	Part Source	Price SGD
1009	INNER FRT PANEL CPL	641012H000	Supplementary (A) cra✓	280.00
0638	R/F FOG LAMP	922022H000	Original	120.00
0842	R/F WHEELHOUSE COVER	868122H010	Original	50.00
0742	R/F WING	663212H022	Original	220.00
0812	R/F WING BADGE	863162H000	Original	20.00
0562	RIGHT HEADLAMP ASSY	921022H090	Original	280.00
0328	RIGHT RETAINER	1491005000	Original	30.00
1437	W-SCREEN WASHER PUMP	985102G000	Supplementary (A) dis ✓	120.00
1436	W-WASHER BOTTLE	986202H000	Original	60.00
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 1,560.00
u: Used parts				Total 1,560.00

Extras

Code	Description	Price SGD
1000	FRT BUMPER CLIPS	40.00*
1001	ALINGMENT	80.00*
Total Extras		120.00

Final Calculation

	SGD	SGD
Parts		
Total Parts	1,560.00	1,560.00
Labour Time Base 10 WU/h		
Total 128.0 WU X 42.00 SGD/h	537.60	
Total of Labour		537.60
Total Of Extras		120.00
Paint Work Time Base 10 WU/h		
Labour Cost 94.0 WU X 42.00 SGD/h	394.80	
Material Cost	180.64	
Total Paint Including Material		575.44
Repair Cost Excludes GST		2,793.04
GST (+9.00%)		251.37
Repair Cost Included GST		3,044.41

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS