

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110346/TUA3Q2
Date: 12/11/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0009399_01
Claimant Vehicle No : SDN7557T Insured Vehicle No : GBM3187H
Date of Loss: 16/11/2024 Nature of Claim: TP Claim No: MFL2024D0013724

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SDN7557T
Make & Model: MERCEDES-BENZ C180, 1.6 AVG (R17 LED) (A) Engine No: 27491031768695
Reg. Date: 26/07/2019 (Man. Year: 2019) Chassis No: WDD2050402R496960
Colour: White Odometer: 78612 km
Engine Capacity: 1595 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/50 R17 Rear Tyre Size: 225/50 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,406.50	1,750.00	1,656.50	48.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,330.00	520.00	1,810.00	77.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,736.50	2,270.00	3,466.50	60.43
Approved Total (Overridden) (S\$)		1,800.00		
(S\$)	5,736.50	1,800.00	3,936.50	68.62
+ GST 9.00/9.00% (S\$)	516.29	162.00	354.29	68.62
Nett Amount (S\$)	6,252.79	1,962.00	4,290.79	68.62
+ Loss of Use (2.0 x S\$80.00/day) (S\$)		160.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		2,124.18		
Global Sum Settlement (S\$)		2,120.00		

INSPECTION

Date of Assignment: 04/12/2024
Date Inspected: 04/12/2024 Inspected At: Accord Auto Services Pte Ltd (Bukit Merah)
BLK 1009 BUKIT MERAH LANE 3, #01-80
Singapore 159723
Estimated Period of Repair: 2.0 days

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Jan 2025)
Parts:	143	MERCEDES-BENZ C180 1.6 AVG (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDN7557T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH LAMP	Not Necessary	950.00 FL	*- FL
2	1		*REAR RH SIDE RETAINER	Not Necessary	115.00 FL	*- FL
3	1		*REAR BUMPER	Deformed	2,450.00 FL	*1,850.00 FL
4	1		*SET REAR BUMPER SENSOR SEAL	Necessary	50.00 FL	*50.00 FL
5	1		*REAR BUMPER TOW COVER	Not Necessary	120.00 FL	*- FL
6	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FS	*40.00 FS
7	1		*SET CAR PLATE NUMBER WITH FRAME	Not Necessary	50.00 FS	*- FS
					Sub Total (\$\$)	3,775.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	368.50
					Total Parts (\$\$)	3,406.50
						1,940.00
						1,750.00

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING TO ALL AFFECTED AREAS	New	600.00	250.00
2	LABOUR REMOVE /REFIX ACCIDENT DAMAGES PARTS TO KNOCK ,JACK CUT WELD AND REALIGN ACCIDENT AFFECTED AREA	New	800.00	200.00
3	CHECK WIRING SYSTEM & LIGHT	New	100.00	30.00
4	ANTI RUST TREATMENT	New	120.00	0.00
5	TO REMOVE/REFIX REAR INNER COMPARTMENT TO FACILITATE REPAIR	New	150.00	0.00
6	TO REMOVE/REPLACE/REFIX REAR REVERSE SENSOR	New	180.00	40.00
7	COMPUTER DIAGNOSTIC (RESET NECESSARY ELECTRONIC FUNCTION)	New	380.00	0.00
Gross Labour Cost (\$\$)			2,330.00	520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >