

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

ECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600

Our File No: CS/ICS24110348/ENP3M4**Date:** 19/12/2024REFERENCE

Insured/Claimant: KOH BEE SOCK Policy No: MPC24P00421700
Date of Loss: 11/11/2024 Nature of Claim: OD Claim No: DMPC2401548H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SNM701B**
Make & Model: MERCEDES-BENZ C180, 1.6 Avantgarde (R17 LED) (A) Engine No: 27491030247273
Reg. Date: 05/11/2014 (Man. Year: 2014) Chassis No: WDD2050402R015232
Colour: Black Odometer: 215870 km
Engine Capacity: 1595 cc
Market Value/New Car Price: S\$131,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45ZR18 Rear Tyre Size: 225/45ZR18
Front Left Side: landspider 5 mm Rear Left Side: landspider 5 mm
Front Right Side: landspider 5 mm Rear Right Side: landspider 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,567.70	10,259.70	308.00	2.91
Miscellaneous Items	195.00	165.00	30.00	15.38
Paintwork Materials	120.00	0.00	120.00	100.00
Labour	1,250.00	700.00	550.00	44.00
Paintwork Labour	600.00	400.00	200.00	33.33
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,732.70	11,524.70	1,208.00	9.49
Approved Total (Overridden) (S\$)		9,200.00		
- Excess (S\$)	0.00	750.00	-750.00	
(S\$)	12,732.70	8,450.00	4,282.70	33.64
+ GST 9.00/9.00% (S\$)	1,145.94	760.50	385.44	33.64
Nett Amount (S\$)	13,878.64	9,210.50	4,668.14	33.64

INSPECTION

Date of Assignment: 18/11/2024 Present Location: Dickson Auto Care Centre Pte Ltd (HQ)
Date Inspected: 21/11/2024 Inspected At: DICKSON AUTO CARE CENTRE PTE LTD (HQ)
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Dec 2024)
Parts:	143	MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNM701B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		Air-cond condenser (WCP)	Bent	770.00 F	*770.00 F
2	1		Bonnet (WCP)	Dented	1,100.00 F	*1,100.00 F
3	10		Bumper clip, front (WCP)	Necessary	50.00 F	*50.00 F
4	1		Bumper reinforcement, front (WCP)	Dented	250.00 F	*250.00 F
5	1		Bumper, front (WCP)	Broken	820.00 F	*820.00 F
6	1		Headlamp LH (WCP)	Broken	1,720.00 F	*1,720.00 F
7	1		Headlamp RH (WCP)	Broken	1,720.00 F	*1,720.00 F
8	1		Panel, front (WCP)	Bent	420.00 F	*420.00 F
9	1		*Grille Front (WCP)	Broken	75.00 F	*75.00 F
10	1		*Grille Front Cover (WCP)	Broken	125.00 F	*125.00 F
11	4		*Grille Front Moulding (WCP)	Cut	260.00 F	*260.00 F
12	1		*Grille Badge [Logo] (WCP)	Missing	75.00 F	*75.00 F
13	1		*Grille Badge Bracket (WCP)	Missing	48.00 F	*48.00 F
14	1		*Bumper Shock Absorber Front (WCP)	Broken	150.00 F	*150.00 F
15	1		*Bonnet Badge [Logo] (WCP)	Necessary	45.00 F	*45.00 F
16	1		*Number Base Plate Front (WCP)	Not Necessary	90.00 F	*- F
17	1		*Grille Front Upper Cover (WCP)	Not Necessary	70.00 F	*- F
<u>Supplementary #1</u>						
18	1		*BUMPER BRACKET FRONT RH [BELOW HEADLAMP] (WCP)	Broken	55.00 F	*55.00 F
19	1		*BUMPER FRONT UNDERCOVER (WCP) (NOT NECESSARY)	Old Damaged	120.00 F	*- F
20	1		*TOP GRILLE SUPPORT [INNER] (WCP)	Bent	155.00 F	*155.00 F
21	1		*BUMPER SIDE RETAINER FRONT LH (WCP)	Broken	12.00 F	*12.00 F
22	1		*BUMPER SIDE RETAINER FRONT RH (WCP)	Broken	12.00 F	*12.00 F
23	1		*GRILLE RUBBER COVER (WCP)	Broken	95.00 F	*95.00 F
24	1		*LOWER GRILLE (WCP)	Broken	90.00 F	*90.00 F
25	8		*RIVET (WCP)	Necessary	40.00 F	*40.00 F
<u>Supplementary #2</u>						
26	1		*LOW TEMP RADIATOR [CENTRE] (WCP)	Bent	540.00 F	*540.00 F
Report was unsubmitted during this print-out.						

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
27	1		*RADIATOR (WCP)	Bent	650.00 F	*650.00 F
28	1		*RADIATOR UPPER FLOW HOSE (WCP)	Deformed	50.00 F	*50.00 F
F=Franchise part.						
Sub Total (\$\$)					9,607.00	9,327.00
+ Margin on L,N Items 10.00/10.00% (\$\$)					960.70	932.70
Total Parts (\$\$)					10,567.70	10,259.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Materials</u>				
1	1	Paintwork Materials Not Necessary	120.00	0.00
<u>Miscellaneous Items</u>				
2	1	Air-cond gas (R134A) Necessary	60.00	60.00
3	1	Electrical (check & diagnose) Necessary	17.50	17.50
4	1	Number plate front holder Cut	25.00	25.00
5	1	Number plate, front Broken	12.50	12.50
<u>Supplementary #2</u>				
6	1	Radiator coolant Necessary	80.00	50.00
Sub Total (\$\$)			315.00	165.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Bonnet	New	350.00	200.00
2	Bumper, front	New	250.00	200.00
<u>Labour Items</u>				
3	Bonnet }	New	300.00	700.00
4	Bumper, front }	New	250.00	0.00
5	Cooling system }	New	200.00	0.00
6	Bumper reinforcement, front }	New	100.00	0.00
7	Headlamps Front }	New	100.00	0.00
8	Panel, front }	New	300.00	0.00
Gross Labour Cost (\$\$)			1,850.00	1,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >