

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG24110350/RNP3M4**Date:** 14/01/2025REFERENCE

Insured/Claimant:	TAN CHOON SIONG	Policy No:	7210021293	
Date of Loss:	16/11/2024	Nature of Claim:	OD	Claim No: 2201046472SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMY3418Z		Engine No:	CZDC25465
Make & Model:	AUDI Q3, 1.4 TFSI S TRONIC (17") (A)		Chassis No:	WAUZZZF33M1067112
Reg. Date:	26/02/2021 (Man. Year: 2020)		Odometer:	40472 km
Colour:	Red			
Engine Capacity:	1395 cc			
Market Value/New Car Price:	S\$129,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50R19	Rear Tyre Size:	235/50R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre tread depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,122.00	10,225.44	9,896.56	49.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,322.00	2,872.00	4,450.00	60.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,444.00	13,097.44	14,346.56	52.28
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	27,044.00	12,697.44	14,346.56	53.05
+ GST 9.00/9.00% (S\$)	2,433.96	1,142.77	1,291.19	53.05
Nett Amount (S\$)	29,477.96	13,840.21	15,637.75	53.05

INSPECTION

Date of Assignment:	18/11/2024	
Date Inspected:	18/11/2024	Inspected At: 24 BENOI SECTOR SINGAPORE 629857 REPAIRER: PREMIUM AUTOMOBILES PTE LTD
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL**Manager:** HUEY YON

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,388.00 FS	*1,110.00 FS
2	1		*FRONT BUMPER CLOSING ELEMENT - LH	Cracked	74.00 FS	*59.04 FS
3	1		*FRONT BUMPER GRILLE - LH	Scratched	139.00 FS	*110.80 FS
4	1		*FRONT BUMPER CLOSING ELEMENT	Serviceable	238.00 FS	*- FS
5	1		*FRONT BUMPER SPOILER	Scratched	479.00 FS	*382.80 FS
6	1		*FRONT BUMPER BRACKET	Not Necessary	27.00 FS	*- FS
7	1		*FRONT BUMPER AIR GUIDE GRILLE - LH	Cracked	192.00 FS	*153.60 FS
8	1		*RADIATOR GRILLE	Cracked	1,795.00 FS	*1,436.00 FS
9	1		*RADIATOR GRILLE, STRIKER PLATE	Cracked	303.00 FS	*242.40 FS
10	1		*FRONT FOAM FILLER PIECE	Serviceable	129.00 FS	*- FS
11	1		*FRONT REINFORCEMENT BEAM	Serviceable	1,116.00 FS	*- FS
12	1		*FRONT BUMPER TOP COVER	Serviceable	154.00 FS	*- FS
13	1		*FRONT BUMPER GUIDE SECTION - LH	Serviceable	49.00 FS	*- FS
14	1		*CAUTION STICKER	Necessary	25.00 FS	*19.44 FS
15	1		*A/C STICKER	Necessary	10.00 FS	*7.52 FS
16	1		*FRONT FENDER- LH	Repair	1,537.00 FS	*- FS
17	1		*FRONT FENDER BRACE - LH	Serviceable	127.00 FS	*- FS
18	1		*FRONT FENDER BRACKET - LH	Serviceable	58.00 FS	*- FS
19	1		*FRONT WHEEL HOUSING LINER - LH FRONT	Serviceable	289.00 FS	*- FS
20	1		*FRONT FENDER COVER - LH	Serviceable	20.00 FS	*- FS
21	1		*FRONT FENDER CLOSING ELEMENT - LH	Serviceable	25.00 FS	*- FS
22	1		*SIGNAL HORN - LH	Serviceable	162.00 FS	*- FS
23	1		*HORN BRACKET - LH	Serviceable	28.00 FS	*- FS
24	1		*HEADLIGHT MOUNTING - LH	Cracked	147.00 FS	*117.60 FS
25	1		*LED HEADLIGHT - LH	Cracked	6,696.00 FS	*5,356.80 FS
26	1		*LED HEADLIGHT POWER MODULE	Serviceable	904.00 FS	*- FS
27	1		*LED HEADLIGHT HEAT SINK - LH	Serviceable	982.00 FS	*- FS
28	1		*HEADLIGHT BREATHER HOSE - LH	Serviceable	31.00 FS	*- FS
29	1		*LIFT CYLINDER - LH	Cracked	244.00 FS	*195.20 FS
30	1		*LIFT CYLINDER HOSE - LH	Serviceable	102.00 FS	*- FS
31	1		*WASH WATER RESERVOIR TANK	Serviceable	269.00 FS	*- FS
32	2		*FRONT PARKING AID SENSOR	Not Working	572.00 FS	*457.60 FS
33	4		*FRONT PARKING AID SENSOR SEAL RING	Necessary	11.00 FS	*8.64 FS
34	1		*SET FRONT BUMPER WIRING	Serviceable	804.00 FS	*- FS
35	2		*FRONT WHEEL ARCH COVER - LH / RH	Necessary	636.00 FS	*508.00 FS
36	1		*FRONT NO PLATE	Necessary	60.00 FS	*60.00 FS
37	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	20,122.00	10,225.44
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS CONTROL UNIT AND POWER MODULE	New	550.00	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	3,000.00	750.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER	New	3,000.00	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			7,322.00	2,872.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >