11/21/25, 1:42 PM Adjuster Report

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24060279/KUA3Q2

**Date:** 21/11/2025

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MPC0008932

Claimant Vehicle SLC7858M Insured Vehicle No: SJU4892L

No:

Date of Loss: 25/06/2024 Nature of Claim: TP Claim No: MPC2024D0007546

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SLC7858M

 Make & Model:
 TOYOTA COROLLA, 1.5 X AXIO (A)
 Engine No:
 2NR8608166

 Reg. Date:
 25/05/2016 (Man. Year: 2016)
 Chassis No:
 NRE1610017036

 Colour:
 Metallic Silver
 Odometer:
 137002 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16
Front Left Side: Yokohama 4 mm Rear Left Side: Yokohama 7 mm
Front Right Side: Yokohama 4 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	763.17	763.17	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	420.00	280.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,463.17	1,183.17	280.00	19.14
Approved Total (Overridden) (S\$)		1,183.18		
(S\$)	1,463.17	1,183.18	279.99	19.14
+ GST 9.00/9.00% (S\$)	131.69	106.49	25.20	19.14
Nett Amount (S\$)	1,594.86	1,289.67	305.19	19.14
+ Car Rental (2.0 x S\$100.00/day + 9	0.00% GST) (S\$)	218.00		
+ Doc/S	Search Fee (S\$)	2.18		
No	ett Liability (S\$)	1,509.85		

**INSPECTION** 

Date of Assignment: 15/07/2024

Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 15/07/2024 Inspected At: Blk 1019 #01-374/382, Yishun Industrial Park A

Singapore 768761

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG Manager: NA MENG YAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

We have checked and confirmed that all part prices are correct. The actual work carried out and listed as labour and spray painting is accurate, and the fees charged for labour and spray painting are correct.

### REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 22 Aug 2024)

Parts: 143 TOYOTA COROLLA 1.5 X AXIO (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLC7858M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	779.40 FL	*779.40 FL
2	1		*REAR BUMPER LH SIDE RETAINER	Cracked	150.50 FL	*150.50 FL
3	6		*REAR BUMPER CLIP	Necessary	21.00 FL	*21.00 FL
4	1		*REAR BUMPER LH BODY PROTECTOR	Necessary	50.00 FS	*50.00 FS
F=Fra	anchise	part. S=SpcNe	ett. L=ListItemDisc.	_		
				Sub Total (S\$)	1,000.90	1,000.90
			- List Item Discount on L Items 2	5.00/25.00% (S\$)	237.73	237.73
				Total Parts (S\$)	763.17	763.17
			Report was unsubmitted during this p	rint-out.		

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	our Items					
1	REMOVE & REFIX REAR BUMPER ,REVERSE SENSOR ASSY ,KNOCKING & REPAIR REAR LH FENDER LOWER & REALIGN THE SAME	New E	300.00	200.00		
2	PUTTY & RESPRAY ON REAR BUMPER ,REAR LH FENDER	New	400.00	220.00		
	Gross Labour Cost (S\$)		700.00	420.00		
Report was unsubmitted during this print-out.						

< END OF ESTIMATES >