

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/III24110353/UNP3E2
Date: 05/12/2024REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	
Claimant Vehicle No :	SLR1131L	Insured Vehicle No :	PC4020K
Date of Loss:	15/11/2024	Nature of Claim:	TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR1131L	Engine No:	LEB5255384
Make & Model:	HONDA GRACE HYBRID, 1.5 DX (A)	Chassis No:	GM41105369
Reg. Date:	31/07/2017 (Man. Year: 2016)	Odometer:	71588 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	LAUFENN 6 mm	Rear Left Side:	LAUFENN 6 mm
Front Right Side:	LAUFENN 6 mm	Rear Right Side:	LAUFENN 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,488.00	6,018.00	5,470.00	47.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,640.00	2,220.00	2,420.00	52.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,128.00	8,238.00	7,890.00	48.92
Approved Total (Overridden) (S\$)		6,500.00		
Nett Amount (S\$)	16,128.00	6,500.00	9,628.00	59.70

INSPECTION

Date of Assignment:	18/11/2024	We Garage (HQ)
Date Inspected:	19/11/2024 Inspected At:	1 Kaki Bukit Avenue 6, #02-11 Autobay @ Kaki Bukit Singapore 417883
Estimated Period of Repair:	5.0 days	

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2024)
Parts: 143	HONDA GRACE HYBRID 1.5 DX (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SLR1131L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	115.00 FL	*- FL
2	1		*REAR BOOT LID	Badly Dented	1,288.90 FL	*1,288.90 FL
3	1		*SET REAR BOOT CHROME CLIP	Not Necessary	75.00 FL	*- FL
4	1		*REAR BOOT OUTER CHROME MOULDING	Cracked	320.30 FL	*320.30 FL
5	1		*REAR BOOT TOP SPOILER	Cracked	1,106.90 FL	*600.00 FL
6	1		*REAR BOOT HINGES	O/S Twisted	180.40 FL	*90.20 FL
7	1		*REAR BOOT INNER TRIM	Not Necessary	260.80 FL	*- FL
8	2		*REAR BOOT LAMPS	Cracked	783.80 FL	*783.80 FL
9	1		*REAR BOOT LOGO	Necessary	28.20 FL	*28.20 FL
10	1		*REAR BOOT WEATHERSTRIP	Twisted	129.60 FL	*129.60 FL
11	1		*REAR BOOT GRACE EMBLEM	Necessary	55.60 FL	*55.60 FL
12	1		*REAR BOOT HYBRID EMBLEM	Necessary	68.30 FL	*68.30 FL
13	2		*REAR NUMBER PLATE LAMPS	Cracked	170.00 FL	*170.00 FL
14	2		*REAR TAILLAMPS	Cracked	1,358.80 FL	*900.00 FL
15	1		*REAR TAILLAMP PANELS	O/S Dented / N/S Repair	890.40 FL	*299.00 FL
16	1		*REAR END PANEL	Badly Dented	813.70 FL	*600.00 FL
17	1		*REAR END PANEL INNER GARNISH	Twisted	215.00 FL	*215.00 FL
18	1		*REAR BUMPER	Distorted	1,000.70 FL	*632.50 FL
19	1		*REAR BUMPER INNER SPONGE	Not fitted	99.10 FL	*- FL
20	1		*REAR BUMPER REFLECTORS	O/S Cracked	130.60 FL	*65.30 FL
21	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	97.20 FL	*- FL
22	1		*REAR FLOOR PANEL	Repair	855.30 FL	*- FL
23	1		*REAR FLOOR BOARD	Warped	455.00 FL	*394.20 FL
24	1		*REAR FENDER - RH	Repair	1,414.60 FL	*- FL
25	1		*REAR FENDER INNER TRIM BOARDS (N/S NOT NECESSARY)	O/S Deformed / Torn	801.80 FL	*399.10 FL
26	1		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
27	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
28	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	50.00 FS	*- FS
29	1		*SET REAR REVERSE SENSOR	Malfunction	350.00 FS	*200.00 FS
30	1		*REAR REVERSE CAMERA	Serviceable	600.00 FS	*- FS
31	1		*REAR BOOT INNER LOCK	Twisted	195.00 FL	*195.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	14,070.00	7,465.00
- List Item Discount on L Items 20.00/20.00% (\$)	2,582.00	1,447.00
Total Parts (\$)	11,488.00	6,018.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR AND CAMERA	New	150.00	30.00
4	TO TRANSFER BOOT LID MECHANISM AND WIRING ASSEMBLY	New	80.00	50.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	0.00
6	TO APPLY UNDERCOATING	New	200.00	60.00
7	PANEL BEATING	New	2,000.00	800.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,800.00	1,200.00
Gross Labour Cost (\$)			4,640.00	2,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >