

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI24110354/AVP3Q2**Date:** 18/02/2025REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SNK4409E**Insured Vehicle No :** GT3399S

Date of Loss: 13/11/2024

Nature of Claim:

TP

Claim No: CDMCG24002942

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNK4409E**

Make & Model: MINI COOPER, 1.5 (A)

Engine No: 37219460B38A15A

Reg. Date: 25/02/2016 (Man. Year: 2015)

Chassis No: WMWXS520002C89095

Colour: White

Odometer: 113884 km

Engine Capacity: 1499 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/55 R16

Rear Tyre Size: 195/55 R16

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,509.15	3,636.00	5,873.15	61.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,180.00	1,110.00	2,070.00	65.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,689.15	4,746.00	7,943.15	62.60
Approved Total (Overridden) (S\$)		3,800.00		
Nett Amount (S\$)	12,689.15	3,800.00	8,889.15	70.05

INSPECTION

Date of Assignment: 18/11/2024

Date Inspected: 18/11/2024

Inspected At:

Fong Motors - Kaki Bukit (HQ)

1 KAKI BUKIT AVE 6 #01-27/01-45

Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Feb 2025)
Parts:	144	MINI COOPER 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNK4409E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	914.00 FL	*914.00 FL
2	2		*REAR BUMPER SIDE HOLDER	Not Necessary	90.00 FL	*- FL
3	1		*REAR BUMPER INNER BRACKET	N/S Cracked	362.00 FL	*181.00 FL
4	2		*REAR BUMPER REFLECTOR	Not Necessary	152.00 FL	*- FL
5	1		*REAR BUMPER REFLECTOR CHROME RING	Not Necessary	92.00 FL	*- FL
6	2		*REAR BUMPER TOW COVER	Repair	76.00 FL	*- FL
7	4		*REAR BUMPER SENSOR	Damaged (1 PCS ONLY)	1,004.00 FL	*251.00 FL
8	4		*REAR BUMPER SENSOR HOLDER	Necessary	100.00 FL	*100.00 FL
9	1		*REAR BUMPER LOWER GARNISH	Deformed	285.00 FL	*285.00 FL
10	1		*REAR END PANEL	Not Necessary	512.00 FL	*- FL
11	1		*REAR END PANEL TOP GARNISH	Not Necessary	159.00 FL	*- FL
12	1		*TAILLAMP	N/S Cracked	996.00 FL	*498.00 FL
13	2		*TAILLAMP CHROME RING	Not Necessary	108.00 FL	*- FL
14	1		*TAILGATE	Dented	1,245.00 FL	*1,245.00 FL
15	1		*TAILGATE LOCK	Damaged	192.00 FL	*192.00 FL
16	1		*TAILGATE WEATHERSTRIPE	Not Necessary	209.00 FL	*- FL
17	1		*TAILGATE INNER TRIM BOARD	Not Necessary	405.00 FL	*- FL
18	1		*TAILGATE GLASS MOULDING	Necessary	185.00 FL	*185.00 FL
19	1		*COOPER WORDING	Necessary	89.00 FL	*89.00 FL
20	1		*REAR EXHAUST PIPE	Not Necessary	1,090.00 FL	*- FL
21	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	54.00 FL	*- FL
22	1		*REAR EXHAUST PIPE GASKET	Not Necessary	45.00 FL	*- FL
23	1		*REAR EXHAUST PIPE HEAT SHIELD	Not Necessary	124.10 FL	*- FL
24	2		*REAR FENDER ARC GARNISH	Not Necessary	392.00 FL	*- FL
25	2		*REAR FENDER INNER SHIELD	Not Necessary	295.00 FL	*- FL
26	2		*REAR FENDER INNER TRIM BOARD	Not Necessary	610.40 FL	*- FL
27	1		*REAR BUMPER REINFORCEMENT	Not Necessary	558.00 FL	*- FL
28	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
29	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
30	1		*REAR END PANEL SEALANT	Not Necessary	60.00 FS	*- FS
31	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS
32	1		*TAILGATE GLASS SEALANT	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	10,543.50	4,030.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,034.35	394.00
Total Parts (\$\$)	9,509.15	3,636.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVE AND REFIT PARTS	New	1,200.00	450.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,000.00	400.00
3	WIRING CHECK	New	100.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	50.00
5	TO REMOVE UPHOLSTERY	New	150.00	0.00
6	TO SPRAY TUFF COAT	New	150.00	0.00
7	TO REMOVE REAR EXHAUST PIPE	New	150.00	0.00
8	TO TRANSFER TAILGATE FITTINGS	New	150.00	60.00
9	TO REPLACE TAILGATE GLASS	New	180.00	120.00
Gross Labour Cost (\$\$)			3,180.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >