3/28/25, 9:25 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110357/EUA3Q2

Date: 28/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_05

Claimant Vehicle GBD3058U Insured Vehicle No: GBK2992S

No:

Date of Loss: 15/11/2024 Nature of Claim: TP Claim No: MFL2024D0013636

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBD3058U**

NISSAN CABSTAR, 3.0 D 5M/T ABS 2DR 2WD

Make & Model: Engine No: ZD30340912K EURO 5 (M)

Reg. Date: 29/08/2014 (Man. Year: 2014) Chassis No: JN1SC2F24Z0856186 409724 km

Colour: Silver Odometer: 2953 cc

Engine Capacity: Market Value/New Car N/A

Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15

Front Left Side: Rear Left Side: Bridgestone 5 mm Bridgestone 5 mm Rear Right Side: Front Right Side: Bridgestone 5 mm Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,090.70	7,299.19	8,791.51	54.64
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,130.00	2,610.00	6,520.00	71.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,220.70	9,909.19	15,311.51	60.71
Approved Total (Overridden) (S\$)		7,950.00		
(S\$)	25,220.70	7,950.00	17,270.70	68.48
+ GST 9.00/9.00% (S\$)	2,269.86	715.50	1,554.36	68.48
Nett Amount (S\$)	27,490.56	8,665.50	18,825.06	68.48
+ Loss of Use (10.0 x	S\$80.00/day) (S\$)	800.00		
+ Doc/Search Fee (S\$)		58.25		
	Nett Liability (S\$)	9,523.75		
Global Sui	m Settlement (S\$)	9,500.00		

INSPECTION

Date of Assignment: 20/11/2024

R&S AUTOCLAIM PTE LTD (HQ) Date Inspected: 20/11/2024 Inspected At: 13 PIONEER SECTOR 1, SINGAPORE 628424

Singapore 628424

Estimated Period of Repair: 10.0 days

Adjuster: **CHEN TSUE YEE** Manager: NA MENG YAN NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 24 Feb 2025)

Parts: NISSAN CABSTAR 3.0 D 5M/T ABS 2DR 2WD EURO 5 (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBD3058U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty Part N	o. Particulars	Condition	Repairer's	Amount
1	1	*WIPER PANEL	Dented	684.00 F	*588.00 FL
2	1	*WIPER PANEL RUBBER	Not Necessary	54.80 F	*- FL
3	1	*SET WIPER PANEL CLIPS	Not Necessary	50.00 F	*- FL
ļ	1	*FRONT PANEL	Dented	1,583.60 F	*1,583.60 FL
;	1	*FRONT PANEL EMBLEM -CABSTAR	Necessary	95.80 F	*95.80 FL
6	1	*FRONT GRILLE	Cut	477.00 F	*477.00 FL
,	1	*FRONT GRILLE SEAL (NPA)	Not Necessary	0.00 F	*- FL
3	1	*FRONT GRILLE RUBBER (NPA)	Not Necessary	0.00 F	*- FL
)	1	*FRONT GRILLE CENTER BRACKET	Not Necessary	72.60 F	*- FL
0	2	*FRONT GRILLE SIDE COVER	Not Necessary	234.20 F	*- FL
1	2	*SET FRONT GRILLE SIDE COVER CLIPS	Not Necessary	100.00 F	*- FL
2	1	*FRONT GRILLE EMBLEM LOGO	Necessary	94.30 F	*94.30 FL
3	2	*FRONT CORNER PANEL LH/RH	Not Necessary	914.20 F	*- FL
4	2	*SET FRONT CORNER PANEL CLIPS	Not Necessary	100.00 F	*- FL
5	1	*FRONT BUMPER	Dented	903.10 F	*903.10 FL
6	1	*SET FRONT BUMPER CLIPS	Not Necessary	50.00 F	*- FL
7	2	*FRONT BUMPER STIFFENER (NPA)	Not Necessary	0.00 F	*- FL
8	1	*FRONT BUMPER REINFORCEMENT	Bent	805.50 F	*521.00 FL
9	2	*SIDE MIRROR STAY COVER	Not Necessary	178.00 F	*- FL
20	2	*SIDE MIRROR STAY COVER BRACKET	Not Necessary	30.00 F	*- FL
1	1	*HEAD LAMP ASSY LH/RH	O/S Broken	806.20 F	*403.10 FL
22	2	*FRONT DOOR	Not Necessary	3,279.60 F	*- FL
23	2	*FRONT DOOR SIGNAL LAMP	Not Necessary	121.60 F	*- FL
24	1	*REAR TAIL LAMP RH	Broken	153.20 F	*153.20 FL
25	 1	*FRONT NUMBER PLATE	Bent	35.00 FS	*35.00 FS
26	2	*FRONT DOOR COMPANY DETAIL STICKER	Necessary	60.00 FS	*60.00 FS
27	1	*SIDE GATE RH	Repair	1,102.00 FS	*- FS
28	1	*SIDE RAILING RH (CHROME)	Broken	800.00 FS	*600.00 FS
9	1	*REAR GATE LOWER LOCK RH	Bent	187.00 FS	*187.00 FS
0	1	*TAILGATE	Dented	1,525.00 FS	*1,525.00 FS
1	3	*TAILGATE HINGE	Not Necessary	369.00 FS	*- FS
2	1	*REAR STEP PANEL	Repair	450.00 FS	*- FS
3	1	*REAR TAIL LAMP BRACKET	Bent	115.00 FS	*115.00 FS
34	1	*REAR NUMBER PLATE		35.00 FS	*- FS
		*REAR NUMBER PLATE BRACKET	Not Necessary		
5 6	1	*REVERSE SENSOR	Not Necessary Shorted / Cut	35.00 FS	*- FS
	1			350.00 FS	*200.00 FS
7	1	*NISSAN STICKER	Necessary	180.00 FS	*180.00 FS
8	1	*8 PAX STICKER	Necessary	30.00 FS	*30.00 FS
89	1	*70KM/H STICKER	Necessary	30.00 FS	*30.00 FS
0	1	*REAR BODY BED PANEL (NPA)	Repair	0.00 FS	*- FS
l1 ≔Fra	1 anchise part. S=S	*REAR CANOPY (NPA) pcNett. L=ListItemDisc.	Repair	0.00 FS	*- FS
. •	ļ ·	•	Sub Total (S\$)	16,090.70	7,781.10
			L Items 0.00/10.00% (S\$)	0.00	481.91

Total Parts (S\$) 16,090.70 7,299.19

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
					,	

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	TO STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREA ,FRONT PORTION	New	1,800.00	800.00
2	TO PUTTY ,RESPRAY AND POLISH ON ACCIDENT AREA FRONT PORTION	New	1,800.00	500.00
3	TO CHECK AND RECTIFY WIRING CONNECT AND DISCONNECT	New	180.00	30.00
4	TO STRAIGHTEN AND PANEL BEAT ON ACCIDENT AREA ,REAR PORTION	New	900.00	600.00
5	TO PUTTY ,RE-SPRAY PAINTING AND POLISH ON ACCIDENT AREA REAR PORTION	New	1,500.00	500.00
6	TO SPRAY RUST PROOFING ON AFFECTED AREA	New	250.00	30.00
7	TO REMOVE AND INSTALL REAR BODY	New	900.00	0.00
8	TO REMOVE AND INSTALL CANOPY	New	1,800.00	150.00
	Gross Labou	ur Cost (S\$)	9,130.00	2,610.00
	Report was unsubmitted during this	print-out.		

< END OF ESTIMATES >