

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110358/DPA3Q2
Date: 26/05/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D22MFL0002663_02
Claimant Vehicle No : SHB6604M Insured Vehicle No : SKR6739M
Date of Loss: 17/11/2024 Nature of Claim: TP Claim No: MFL2024D0013815

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB6604M
Make & Model: HYUNDAI AE IONIQ HEV, 1.6 DCT (A) Engine No: G4LEJU046400
Reg. Date: 02/04/2019 (Man. Year: 2019) Chassis No: KMHC851CVKU141584
Colour: Blue Odometer: 800011 km
Engine Capacity: 1580 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,774.74	5,250.24	8,524.50	61.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,470.00	1,750.00	2,720.00	60.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,244.74	7,000.24	11,244.50	61.63
Approved Total (Overridden) (S\$)		5,600.00		
(S\$)	18,244.74	5,600.00	12,644.74	69.31
+ GST 9.00/9.00% (S\$)	1,642.03	504.00	1,138.03	69.31
Nett Amount (S\$)	19,886.77	6,104.00	13,782.77	69.31
+ Car Rental (9.0 x S\$114.78/day) (S\$)		1,033.02		
+ Loss of Earnings (9.0 x S\$40.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		27.25		
+ Other Costs (S\$)		80.00		
Nett Liability (S\$)		7,604.27		

INSPECTION

Date of Assignment: 20/11/2024
Date Inspected: 20/11/2024 Inspected At: BIFROST AUTO PTE LTD - LOYANG (HQ)
59 Loyang Drive Level 4 Room 7
Singapore 508969
Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Mar 2025)
Parts:	143	HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHB6604M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Bent	2,549.70 FL	*2,549.70 FL
2	1		*BOOT LID RUBBER	Deformed	187.40 FL	*187.40 FL
3	1		*BOOT LID LOCK UPPER	Damaged	224.00 FL	*224.00 FL
4	1		*BOOT LID H EMBLEM	Necessary	28.00 FL	*28.00 FL
5	1		*EMBLEM HYBRID	Necessary	24.30 FL	*24.30 FL
6	1		*EMBLEM LONIQ	Necessary	31.30 FL	*31.30 FL
7	2		*BOOT LID LAMP (LH/RH)	Not Necessary	1,644.00 FL	*- FL
8	1		*BOOT LID TRIMBOARD	Not Necessary	259.70 FL	*- FL
9	10		*BOOT LID TRIMBOARD CLIPS	Not Necessary	11.00 FL	*- FL
10	1		*BOOT LID TRIMBOARD CENTRE	Not Necessary	159.60 FL	*- FL
11	2		*BOOT LID TRIMBOARD SIDE (LH/RH)	Not Necessary	185.00 FL	*- FL
12	1		*BOOT LID TRIMBOARD REAR	Not Necessary	124.80 FL	*- FL
13	1		*BOOT LID GLASS UPPER MOULDING	Not Necessary	186.30 FL	*- FL
14	1		*BOOT LID GLASS LOWER MOULDING	Not Necessary	145.20 FL	*- FL
15	1		*REAR BUMPER	Broken	459.40 FL	*459.40 FL
16	1		*REAR BUMPER REINFORCEMENT	Broken	394.80 FL	*394.80 FL
17	2		*REAR BUMPER REINFORCEMENT BRACKET (LH/RH)	Broken / Bent	376.20 FL	*376.20 FL
18	1		*ANTENNA ASSY -SMARTK OUTER	Not Necessary	689.50 FL	*- FL
19	1		*REAR BUMPER CENTRE MOULDING ASSY	Broken	451.25 FL	*451.25 FL
20	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Mtg Broken	155.00 FL	*155.00 FL
21	1		*REAR BUMPER ASSY	Not Necessary	138.10 FL	*- FL
22	2		*REAR BUMPER SIDE RETAINER (LH/RH)	Not Necessary	171.60 FL	*- FL
23	1		*REAR BUMPER COVER CLIPS	Necessary	22.00 FL	*22.00 FL
24	1		*REAR BUMPER UNDER CENTRE	Mtg Broken	123.85 FL	*123.85 FL
25	2		*REAR BUMPER SIDE UNDER (LH/RH)	Not Necessary	246.20 FL	*- FL
26	1		*REAR BUMPER REAR HOOK	Not Necessary	94.60 FL	*- FL
27	2		*REAR BUMPER REFLECTOR LAMP (LH/RH)	Not Necessary	165.80 FL	*- FL
28	1		*REAR BUMPER TOWING COVER	Not Necessary	98.80 FL	*- FL
29	1		*REAR BUMPER REVERSE LIGHT (PARKING BRAKE LIGHT)	Socket Broken	328.60 FL	*328.60 FL
30	1		*LICENCE LAMP	Not Necessary	193.53 FL	*- FL
31	1		*LICENCE LAMP WIRE	Not Necessary	135.80 FL	*- FL
32	2		*TAIL LAMP (LH/RH)	Not Necessary	1,870.80 FL	*- FL
33	2		*TAIL LAMP QUARTER PANEL (LH/RH)	Not Necessary	417.80 FL	*- FL
34	1		*REAR PANEL	Dented	532.00 FL	*532.00 FL
35	1		*ANTENNA ASSY -TRUNK	Not Necessary	689.50 FL	*- FL
36	1		*REAR PANEL GARNISH	Not Necessary	346.80 FL	*- FL
37	1		*REAR TRAY TOOLS BOX RH	Not Necessary	675.30 FL	*- FL
38	1		*REAR TRAY TOOLS BOX LH	Not Necessary	693.20 FL	*- FL
39	1		*REAR TRAY LUGGS CENTER	Not Necessary	354.20 FL	*- FL
40	1		*EXHAUST SILENCER	Not Necessary	943.50 FL	*- FL
41	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS
42	1		*REAR BUMPER REVERSE SENSOR	Damaged	180.00 FS	*180.00 FS
43	2		*REAR WINDSCREEN SEALANT	Necessary	92.00 FS	*80.00 FS
44	1		*REAR NO PLATE +TRIM COVER	Broken	45.00 FS	*45.00 FS
45	1		*BOOT LID COMFORT LOGO & TEL NO STICKER	Necessary	35.00 FS	*35.00 FS
46	1		*BOOT LID COMFORT CABLINK TEL NO STICKER	Necessary	30.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*BOOT LID ADVERTISEMENT LOGO	Necessary	120.00 FS	*120.00 FS
			F=Franchise part. S=SpcNett. L=ListItemDisc.			
					Sub Total (S\$)	17,080.43
					- List Item Discount on L Items 20.00/20.00% (S\$)	3,305.69
					Total Parts (S\$)	13,774.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	1,800.00	800.00
2	SPRAY PAINTING CHARGE	New	1,400.00	800.00
3	WIRING CHARGE	New	100.00	0.00
4	TUFF KOTE	New	100.00	30.00
5	TOWING CHARGE	New	80.00	0.00
6	REMOVE/REFIX REAR WINDSCREEN GLASS	New	240.00	80.00
7	REMOVE/REFIX REVERSE SENSOR	New	120.00	40.00
8	REMOVE/REFIX EXHAUST PIPE	New	80.00	0.00
9	DIAGNOSTIC & RESETTING TO ERASE FAULT CODE	New	550.00	0.00
Gross Labour Cost (\$\$)			4,470.00	1,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >