

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD INV No. AC2503845

3 ANSON ROAD #16-00 INV Date 19/06/2025

SPRINGLEAF TOWER Reference CD/CTI24110361/Kua3q2 SINGAPORE 079909

CTI Code

PROFESSIONAL SERVICE FEE

Vehicle No. GBK 6737L

Insured Veh. PA 5250S

Claim No. SNM24D206363

Policy No. DMB1SNW00002292402

Accident Date 11/11/2024

Inspection Date 20/11/2024

| Description | Total |
|--------------------------------|--------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (9%) | 36.00 |
| Grand Total | 436.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | Affiliated to Federation Internationale Des Experts En Automobile | | | | | |
|-----|---------------------------------------------------------------------------------------------------------------------------------------|----------------------------------|-----------------|-----------------------|--|--|
| MS | CHINA TAIPING INS | SURANCE (S) PTE LTD | Ref: | CD/CTI24110361/Kua3q2 | | |
| | 3 ANSON ROAD #1 | 6-00 ER SINGAPORE 079909 | Date: | 19/06/2025 | | |
| | SPRINGLEAF TOW | ER SINGAPORE 0/9909 | Code: | СТІ | | |
| 1. | 1. Policy Particulars :- DIRECT SETTLEMENT | | | | | |
| | Insured Veh. | PA 5250S | Veh. Inspected | GBK 6737L | | |
| | Policy No. | DMB1SNW00002292402 | Coverage | 0 | | |
| | Claim No. | SNM24D206363 | Excess | \$0.00 | | |
| | Assign From | PHOEBE XIE | Assign Date | 19/11/2024 | | |
| 2. | | Vehicle | Details | | | |
| | Make & Model | TOYOTA HIACE VAN TURBO 5DR MT | c.c | 2982 | | |
| | Engine No. | 1KDB048730 | Year of Reg. | 14/10/2020 | | |
| | Chassis No. | JTFHT02P600250709 | Colour | SILVER | | |
| | Odometer | 133404 KM | Steering | IN ORDER | | |
| | Brakes | IN ORDER | General | GOOD | | |
| | Modification(s) | RIMS: NIL | | | | |
| 3. | 3. Conditions of Tyres | | | | | |
| | | Size | Make | Balance (mm) | | |
| | R/H Front Tyre | 195 R15 | CONDOR | 6 | | |
| | L/H Front Tyre | 195 R15 | CONDOR | 6 | | |
| | R/H Rear Tyre | 195 R15 | CONDOR | 8 | | |
| | L/H Rear Tyre | 195 R15 | CONDOR | 8 | | |
| 4. | | Description of | of Damages | | | |
| THE | VEHICLE SUSTAIN | ED DAMAGES AT THE N/S BODY. | | | | |
| DAM | AGES SEE DETAIL | S. | | | | |
| 5. | | General In | formation | | | |
| | Accident Date | 11/11/2024 | Inspection Date | 20/11/2024 | | |
| | Survey held at WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644. | | | | | |
| 5a. | | Rema | arks | | | |
| | A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |
| 5b. | 5b. Estimate Days of Repair | | | | | |
| ГСТ | CCTIMATED NODMAL DEDIOD FOR DEDAID: 6 Working Days | | | | | |

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBK 6737L

| | REPLACEMENT OF PARTS | | | | |
|-----|----------------------------|----------------------|------------------------|-------------------|--|
| Qty | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) | |
| 1 | REAR SLIDING DOOR LH | BENT | \$1,880.20 | \$1,690.70 | |
| 1 | REAR DOOR CENTER ROLLER LH | SERVICEABLE | \$151.90 | \$0.00 | |
| 1 | REAR DOOR HANDLE LH | SERVICEABLE | \$169.82 | \$0.00 | |
| 1 | REAR FENDER LOWER PANEL LH | NO SUCH PARTS | \$322.90 | \$0.00 | |
| 1 | REAR FENDER LH | BENT | \$2,385.60 | \$1,875.60 | |
| 1 | REAR FENDER COWLING LH | SERVICEABLE | \$278.10 | \$0.00 | |
| 1 | REAR BUMPER | SERVICEABLE | \$699.30 | \$0.00 | |
| 1 | REAR BUMPER RETAINER LH | SERVICEABLE | \$35.80 | \$0.00 | |
| 1 | TAILAMP LH | SERVICEABLE | \$471.70 | \$0.00 | |
| 1 | TAILAMP PANEL | TO REPAIR SEE LABOUR | \$142.00 | \$0.00 | |
| 1 | TAILAMP BRACKET | SERVICEABLE | \$61.80 | \$0.00 | |
| | LESS 25.00% DISCOUNT | | (\$1,649.78) | (\$891.58) | |
| | | \$4,949.34 | \$2,674.72 | | |

| | Special Nett | | | |
|-----|---------------------------------|-------------|------------------------|-------------------|
| Qty | Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1 | DOOR STICKER -COMPANY NAME (SN) | NECESSARY | \$350.00 | \$150.00 |
| 1 | SET TIRE RIM (SN) | SERVICEABLE | \$340.00 | \$0.00 |
| | | \$690.00 | \$150.00 | |

| Labour | | | |
|--------------------------------------------------------|-----------|------------------------|-------------------|
| Description of Parts | Condition | Workshop Estimate (\$) | Our Adjusted (\$) |
| CHECK ALL WIRING AND LIGHTING SYSTEM | | \$120.00 | \$20.00 |
| PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS | | \$1,000.00 | \$800.00 |
| SPRAY PAINTING ON AFFECTED AREAS | | \$1,000.00 | \$500.00 |
| APPLY ANTI RUST ON AFFECTED AREAS | | \$150.00 | \$60.00 |
| | | \$2,270.00 | \$1,380.00 |

| GRAND TOTAL | \$7,909.34 | \$4,204.72 | |
|----------------------------------------------------------------------|------------|------------|--|
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | \$3,350.00 | |
| Report Ref No: CD/CTI24110361/Kua3g2 | | | |



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 1 of 4)













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 2 of 4)













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 3 of 4)













51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

INSPECTION PHOTOS (Page 4 of 4)







