



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2503772

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 17/06/2025
Reference CD/CTI24110362/Eua3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SG 6116Z
Insured Veh. SKU 8184J
Claim No. SNM24D206455
Policy No. DMPCSNA00067172402
Accident Date 15/11/2024
Inspection Date 19/11/2024

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CD/CTI24110362/Eua3q2(N)	
			Date: 17/06/2025	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SKU 8184J	Veh. Inspected	SG 6116Z
	Policy No.	DMPCSNA00067172402	Coverage (\$)	0.00
	Claim No.	SNM24D206455	Excess (\$)	0.00
	Assign From		Assign Date	19/11/2024
2. Vehicle Particulars & Condition				
	Make & Model	MAN A95	c.c	10518
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	WMAA95ZZXKF008909	Colour	MULTI COLOUR
	Odometer	409882 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/70 R22.5	FIRENZA	5 mm
	L/H Front Tyre	275/70 R22.5	FIRENZA	5 mm
	R/H Rear Tyre	275/70 R22.5	FIRENZA	5 mm
	L/H Rear Tyre	275/70 R22.5	FIRENZA	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/11/2024	Inspection Date	19/11/2024
	Survey held at	STRIDES PREMIER AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SG 6116Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT WINDSCREEN FW3	BROKEN	4,107.50	4,107.50
1	HEADLAMP :RH (RIGHT SIDE) MAN A95 EURO 6	BROKEN	1,675.00	1,675.00
1	FRP FRONT DOME	TO REPAIR SEE LABOUR	3,430.00	-
1	O/S FRP FRONT HEADLAMP COVER	BROKEN	975.00	975.00
1	FRP FRONT BUMPER	TO REPAIR SEE LABOUR	1,875.00	-
	LESS 10% DISCOUNT		-	-675.75
			12,062.50	6,081.75
<u>SPECIAL NETT ITEMS</u>				
1	ACTIVATOR (SN)	NECESSARY	80.00	80.00
10	SEALANT SIKAFLEX @\$37.00 (SN)	NECESSARY	370.00	370.00
1	PRIMER (SIKA 206 G+P) (SN)	NECESSARY	80.00	80.00
			530.00	530.00
<u>LABOUR</u>				
	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS .INCLUSIVE OF THE REPAIR OF FRP FRONT DOME AND FRP FRONT BUMPER .		2,120.00	1,590.00
	PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS.		786.00	616.00
			2,906.00	2,206.00
GRAND TOTAL			15,498.50	8,817.75

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,500.00
---	--	--	-----------------

Report Ref No. CD/CTI24110362/Eua3q2(N)

CHEN TSUE YEE

Automotive Assessor


HO LEONG CHUAN

Automotive Assessor



DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



PHOTOGRAPHS FOR VEHICLE NO. : SG 6116Z



PHOTOGRAPHS FOR VEHICLE NO. : SG 6116Z



PHOTOGRAPHS FOR VEHICLE NO. : SG 6116Z



PHOTOGRAPHS FOR VEHICLE NO. : SG 6116Z



PHOTOGRAPHS FOR VEHICLE NO. : SG 6116Z



PHOTOGRAPHS FOR VEHICLE NO. : SG 6116Z





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SG 6116Z

