2/14/25, 4:20 PM Adjuster Report

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III24110367/UQP3E2

**Date:** 14/02/2025

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd Policy No:

Claimant Vehicle
No: GBM2727G Insured Vehicle No: GBL1932S

Date of Loss: 14/11/2024 Nature of Claim: TP Claim No: N/A

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: GBM2727G

 Make & Model:
 TOYOTA HIACE, 2.0 DX (A)
 Engine No:
 1TR2385209

 Reg. Date:
 27/10/2022 (Man. Year: 2021)
 Chassis No:
 TRH2005048665

Colour: White Odometer: 59109 km

Engine Capacity: 1998 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: Agilis 6 mm Rear Left Side: Agilis 6 mm
Front Right Side: Agilis 6 mm Rear Right Side: Agilis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		15,806.47	8,858.52	6,947.95	43.96
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,910.00	2,820.00	2,090.00	42.57
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	20,716.47	11,678.52	9,037.95	43.63
	Approved Total (Overridden) (S\$)		10,500.00		
	Nett Amount (S\$)	20,716.47	10,500.00	10,216.47	49.32

**INSPECTION** 

Adjuster:

Date of Assignment: 18/11/2024

MARCUS CHUA

Autobay Pte Ltd (Kaki Bukit) (HQ)
Date Inspected: 19/11/2024 Inspected At: 1 Kaki Bukit Ave 6, #02-11

0:----- 447000

SHIAU CHAN

Singapore 417883
Estimated Period of Repair: 15.0 days

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Manager:

2/14/25, 4:20 PM Adjuster Report

### **REPAIR DETAILS**

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Feb 2025)

Parts: 213 TOYOTA HIACE 2.0 DX (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBM2727G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the

END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN GLASS	Shattered	1,290.30 FL	*1,290.30 FL
2	1		*REAR WINDSCREEN MOULDING	No such part	130.50 FL	*-FL
3	1		*REAR TAILGATE	Badly Dented	1,993.50 FL	*1,993.50 FL
4	2		*REAR TAILGATE DAMPERS	Not Necessary	508.40 FL	*-FL
5	1		*REAR TAILGATE INNER TRIM BOARD	Deformed / Torn	286.95 FL	*286.95 FL
6	1		*REAR TAILGATE INNER CENTER LOCK REMOTE	Damaged	438.60 FL	*438.60 FL
7	1		*REAR TAILGATE LOCK COVER	Distorted	58.00 FL	*58.00 FL
8	1		*REAR TAILGATE LOCK	Damaged	223.30 FL	*223.30 FL
9	1		*REAR TAILGATE LOCK CATCH	Not Necessary	65.90 FL	*-FL
10	1		*REAR TAILGATE LOGO	Necessary	61.90 FL	*61.90 FL
11	1		*REAR TAILGATE OUTER GARNISH	Grazed	219.20 FL	*219.20 FL
12	1		*REAR TAILGATE RUBBER	Twisted	328.48 FL	*328.48 FL
13	1		*REAR THIRD BRAKE LAMP	Not Necessary	255.00 FL	*- FL
14	1		*REAR WIPER ARM	Not Necessary	57.60 FL	*- FL
15	1		*REAR WIPER MOTOR	Not Necessary	989.70 FL	*- FL
16	1		*REAR TAILLAMPS	N/S Broken / O/S Not	771.00 FL	
				Necessary		
17	1		*REAR TAILLAMP PANEL N/S	Badly Dented	923.80 FL	
18	1		*REAR TAILLAMP LOWER GARNISHE N/S	Distorted	230.00 FL	
19	1		*REAR TAILLAMP LOWER GARNISH SIDE RETAINER N/S	Cracked	76.80 FL	*76.80 FL
20	1		*REAR BUMPER	Distorted	695.20 FL	*695.20 FL
21	2		*REAR BUMPER BRACKETS	Bent	57.20 FL	*57.20 FL
22	1		*REAR BUMPER SIDE RETAINER N/S	Cracked	132.40 FL	*132.40 FL
23	1		*REAR BUMPER STEP PANEL	Bent	285.00 FL	*285.00 FL
24	1		*REAR END PANEL	Badly Dented	887.90 FL	*616.20 FL
25	1		*REAR END PANEL TOP MOULDING	Not fitted	108.60 FL	*- FL
26	2		*REAR NUMBER PLATE LAMPS	Not Necessary	164.00 FL	*- FL
27	1		*REAR FLOOR PANEL	Repair	1,880.80 FL	*- FL
28	1		*REAR SIDE BODY PANEL - LH	Badly Dented	1,765.50 FL	*1,765.50 FL
29	1		*REAR SIDE PANEL INNER BOARD	Not Necessary	338.70 FL	*- FL
30	1		*REAR SIDE PANEL AIR VENT N/S	Distorted	100.40 FL	*100.40 FL
31	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
32	1		*REAR VIEW CAMERA	Serviceable	600.00 FS	
33	1		*REAR TAILGATE 70KM/H STICKER	Necessary	28.00 FS	
34	1		*REAR WIPER BLADE	Not Necessary	45.00 FS	
35	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	
36	1		*REAR NUMBER PLATE	Bent	50.00 FS	
37	1		*REAR REVERSE CAMERA	Serviceable	450.00 FS	
38	1		*REAR FLOOR ALUMINIUM BOARD	Dented / Bent		*1,300.00 FS
	-		Problett I - Lightem Dice	z chiod / Bolit	5,555.551 0	.,000.0010

 $\label{eq:FF} \textit{F=Franchise part. S=SpcNett. L=ListItemDisc.}$ 

**Sub Total (S\$)** 19,637.63 11,338.03

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
				- List Item Discount on L Items 25.00/25.00% (S\$)	3,831.16	2,479.51
				Total Parts (S\$)	15,806.47	8,858.52
				Report was unsubmitted during this print-out.		

Adjuster Report

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

2/14/25, 4:20 PM

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	120.00	0.00
3	TO REMOVE AND REFIT REAR REVERSE CAMERA	New	150.00	30.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	80.00	60.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
6	TO APPLY UNDERCOATING	New	200.00	90.00
7	PANEL BEATING	New	2,000.00	1,500.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	2,100.00	1,000.00
	Gross Labo	our Cost (S\$)	4,910.00	2,820.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >