

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJX 8548P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR DOOR	DENTED	1,290.00	1,290.00
1	REAR DOOR LOCK	NOT NECESSARY	315.00	-
1	REAR DOOR WEATHERSTRIPE	NOT NECESSARY	198.00	-
1	REAR DOOR INNER TRIM BOARD	NOT NECESSARY	679.00	-
1	REAR DOOR GLASS REGULATOR	NOT NECESSARY	357.00	-
1	REAR FENDER	TO REPAIR SEE LABOUR	981.00	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	135.00	-
	LESS 10% DISCOUNT		-395.50	-129.00
			3,559.50	1,161.00
	SPECIAL NETT ITEMS			
1	SET REAR DOOR INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	30.00	-
1	REAR DOOR VISOR (SN)	NECESSARY	100.00	60.00
1	REAR DOOR BLACK TAPE (SN)	NECESSARY	60.00	60.00
1	ROCKER PANEL OUTER SKIRTING (SN)	NOT NECESSARY	850.00	-
1	SET ROCKER PANEL OUTER SKIRTING CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	60.00	-
1	REAR WHEEL RIM (SN)	CUT	680.00	580.00
1	REAR TYRE (SN)	CUT	300.00	200.00
			2,130.00	900.00
	<u>LABOUR</u>			
	PANEL BEATING, REMOVE AND REFIT PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER.		1,000.00	400.00
	SPRAY PAINTING TO AFFECTED AREA.		1,000.00	400.00
	WIRING CHECK.		50.00	30.00
	TUFF COAT.		150.00	30.00
	TO REMOVE UPHOLSTERY.		150.00	30.00
	TO REMOVE REAR WINDSCREEN.	NOT NECESSARY	1,800.00	-
	TO TRANSFER REAR DOOR FITTINGS.		150.00	80.00

Report Ref No. CS/INC24110368/Avh3m4(N)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO PERFORM WHEEL ALIGNMENT.		150.00	80.00
			4,450.00	1,050.00
	GRAND TOTAL		10,139.50	3,111.00

RECOMMENDED COST OF LUMP SUM REPAIRS		2,500.00
(TO ITS PRE-ACCIDENT CONDITION)		
(CONFIRMED)		

Report Ref No. CS/INC24110368/Avh3m4(N)

TOTAL FOR SPARE PARTS: \$ 5,689.50 \$ 2,061.00 TOTAL FOR LABOUR: \$ 4,450.00 \$ 1,050.00 TOTAL REPAIR COST: \$10,139.50 \$ 3,111.00

XXX.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

The

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.