

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/III24110369/UDP3E2**Date:** 06/12/2024REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

**Claimant Vehicle No :** SNN2660S**Insured Vehicle No :** SHD2079U

Date of Loss: 16/11/2024

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNN2660S**

Make &amp; Model: TOYOTA ALPHARD, 2.5 HYBRID 7-SEATER 2.5X CVT (A)

Engine No: 2AR2872646

Reg. Date: 27/11/2023 (Man. Year: 2023)

Chassis No: AYH300155469

Colour: Black

Odometer: 59442 km

Engine Capacity: 2493 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/60 R17

Rear Tyre Size: 225/60 R17

Front Left Side: Yokohama 6 mm

Rear Left Side: Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side: Yokohama 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	13,977.74	6,234.90	7,742.84	55.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,530.00	1,660.00	3,870.00	69.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>19,507.74</b>	<b>7,894.90</b>	<b>11,612.84</b>	<b>59.53</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>6,300.00</b>		
<b>Nett Amount (\$\$)</b>	<b>19,507.74</b>	<b>6,300.00</b>	<b>13,207.74</b>	<b>67.71</b>

INSPECTION

Date of Assignment: 18/11/2024

Date Inspected: 19/11/2024 Inspected At:

We Garage (HQ)  
1 Kaki Bukit Avenue 6, #02-11 Autobay @ Kaki Bukit  
Singapore 417883

Estimated Period of Repair: 5.0 days

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 06 Dec 2024)
Parts:	M1-MPV	TOYOTA ALPHARD 2.5 HYBRID 7-SEATER 2.5X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNN2660S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR (L)	Badly Dented	2,787.20 FL	*2,787.20 FL
2	1		*REAR DOOR (L) GLASS MOULDING	Not Necessary	295.80 FL	*- FL
3	1		*REAR DOOR (L) INNER BOARD	Deformed / Torn	987.90 FL	*987.90 FL
4	1		*REAR DOOR (L) DOOR LOCK	Not Necessary	509.00 FL	*- FL
5	1		*REAR DOOR (L) OUTER HANDLE	Not Necessary	395.00 FL	*- FL
6	1		*REAR DOOR (L) REGULATOR	Not Necessary	387.60 FL	*- FL
7	1		*REAR DOOR (L) REGULATOR MOTOR	Not Necessary	587.80 FL	*- FL
8	1		*REAR DOOR (L) OUTER PROTECTOR	Cut	330.80 FL	*330.80 FL
9	1		*REAR DOOR (L) STEP GARNISH	Not Necessary	195.60 FL	*- FL
10	1		*REAR DOOR (L) BLACK TAPE	Necessary	120.00 FL	*90.00 FL
11	1		*REAR DOOR (L) KEYLESS SENSOR	Not Necessary	299.80 FL	*- FL
12	1		*ROCKER PANEL (L)	Repair	1,698.70 FL	*- FL
13	1		*REAR FENDER (L)	Repair	1,882.90 FL	*- FL
14	1		*REAR FENDER OUTER PROTECTOR (L)	Distorted	478.50 FL	*280.00 FL
15	1		*REAR FENDER AIR GATE (L)	Not Necessary	98.25 FL	*- FL
16	1		*REAR QUARTER GLASS MOULDING (L)	Not Necessary	98.60 FL	*- FL
17	1		*REAR BUMPER	Repair	1,258.20 FL	*- FL
18	1		*REAR BUMPER SIDE (L)	Not Necessary	558.90 FL	*- FL
19	2		*REAR BUMPER SIDE RETAINER (L/R)	Not Necessary	306.20 FL	*- FL
20	1		*REAR WHEEL RIM (L)	Bent / Cut	1,582.10 FL	*1,582.10 FL
21	1		*REAR WHEEL HUB WITH BEARING (L)	Damaged	835.00 FL	*805.00 FL
22	1		*REAR SHOCK ABSORBER (L)	Twisted	726.80 FL	*315.20 FL
23	1		*REAR KNUCKLE ARM (L)	Bent	935.00 FL	*935.00 FL
24	1		*SET REAR BUMPER CLIPS	Not Necessary	78.00 FS	*- FS
25	1		*REAR TYRE (LOCAL PURCHASE) (\$250.00) (60%)	Cut / Punctured	650.00 FS	*150.00 FS
26	1		*REAR QUARTER GLASS SPONGE TAPE	Not Necessary	65.00 FS	*- FS
27	1		*REAR QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
28	1		*SET REAR FENDER CLIPS	Not Necessary	88.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,316.65	8,263.20
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,338.91	2,028.30
Total Parts (\$\$)	13,977.74	6,234.90

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	0.00
2	TO REMOVE, REFIT DOOR FITTINGS & REPLACED DAMAGED PARTS, TRANSFER ALL FITTINGS TO NEW DOOR	New	500.00	80.00
3	TO CHECK REAR DOOR WIRING	New	120.00	20.00
4	TO REMOVE, REFIX REAR QUARTER GLASS	New	180.00	0.00
5	TO REMOVE, REFIX REAR UNDERCARRIAGE	New	250.00	120.00
6	TO CONDUCT WHEEL ALIGNMENT	New	180.00	100.00
7	TO RESPRAY UNDERCOATING	New	120.00	40.00
8	PANEL BEATING	New	2,000.00	500.00
9	SPRAY PAINTING	New	2,000.00	800.00
<b>Gross Labour Cost (S\$)</b>			<b>5,530.00</b>	<b>1,660.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >