

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO GBL 928L

	REPLACEMENT OF PARTS						
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)			
2	RAILING BARING	NOT NECESSARY	\$320.00	\$0.00			
1	REAR FENDER LH	TO REPAIR SEE LABOUR	\$2,745.00	\$0.00			
1	REAR FENDER INNER LH	NOT NECESSARY	\$3,210.00	\$0.00			
1	REAR BUMPER	GRAZED	\$625.00	\$625.00			
1	TAILGATE	NOT NECESSARY	\$1,365.00	\$0.00			
1	TAIL GATE LOCK	NOT NECESSARY	\$280.00	\$0.00			
1	REAR TAIL LAMP LH	NOT NECESSARY	\$640.00	\$0.00			
1	REAR TAIL LAMP PANEL LH	NOT NECESSARY	\$270.00	\$0.00			
	LESS 25.00% DISCOUNT		(\$2,363.75)	(\$156.25)			
			\$7,091.25	\$468.75			

Special Nett						
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	REAR RIM LH (SN)	NOT NECESSARY	\$500.00	\$0.00		
1	SIDE DOOR CLIP (SN)	NOT NECESSARY	\$50.00	\$0.00		
1	TAILGATE CLIP (SN)	NOT NECESSARY	\$52.00	\$0.00		
1	JOINT SEALANT (SN)	NOT NECESSARY	\$120.00	\$0.00		
			\$722.00	\$0.00		

Labour					
Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
CHECK ACCIDENT AFFECTED AREA WIRING AND LIGHTING SYSTEM		\$300.00	\$20.00		
REMOVE AND RENEW REAR REVERSE SENSOR	NOT NECESSARY	\$120.00	\$0.00		
REMOVE AND REFIT AND RENEW REAR EXHAUST	NOT NECESSARY	\$150.00	\$0.00		
REMOVE AND REFIT ACCIDENT AFFECTED AREA LINING, TRIM AND GARNISH	NOT NECESSARY	\$300.00	\$0.00		
PANEL BEATING ON REAR ACCIDENT AFFECTED AREAS AND RENEW DAMAGE PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER LH		\$900.00	\$220.00		
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS		\$900.00	\$300.00		
APPLY ANTI RUST ON ACCIDENT AFFECTED AREAS	NOT NECESSARY	\$100.00	\$0.00		
		\$2,770.00	\$540.00		



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

GRAND TOTAL	\$10,583.25	\$1,008.75		
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		\$800.00		
Report Ref No: CS/INC24110370/Uvh3m4				

TOTAL FOR SPARE PARTS: \$ 7,813.25 \$ 468.75
TOTAL FOR LABOUR: \$ 2,770.00 \$ 540.00
TOTAL REPAIR COST: \$10,583.25 \$ 1,008.75

## **CKS**

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.