



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKP 3664A

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT RH DOOR	DENTED	\$1,806.00	\$1,806.00
1	FRONT RH DOOR CHROME MOULDING	NECESSARY	\$186.00	\$186.00
1	FRONT RH DOOR WEATHER STRIP	NECESSARY	\$225.00	\$225.00
1	FRONT RH FENDER 'BLUE EFFICIENCY' EMBLEM	NECESSARY	\$80.00	\$80.00
1	FRONT RH FENDER (ALUMINIUM)	DENTED	\$920.00	\$920.00
1	FRONT RH FENDER CHROME MOULDING	NECESSARY	\$92.00	\$92.00
1	FRONT RH FENDER INNER SHIELD (REAR)	NOT NECESSARY	\$145.00	\$0.00
1	FRONT RH KNUCKLE ARM	NOT NECESSARY	\$796.00	\$0.00
1	FRONT RH KNUCKLE ARM BEARING	NOT NECESSARY	\$525.00	\$0.00
1	FRONT RH LOWER ARM	NOT NECESSARY	\$625.00	\$0.00
1	ROCKER GARNISH RH	NOT NECESSARY	\$526.00	\$0.00
	LESS 10.00% DISCOUNT		(\$592.60)	(\$330.90)
			\$5,333.40	\$2,978.10

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT RH SPORT RIM (SN)	CUT	\$882.00	\$600.00
1	SET FRONT RH FENDER INNER SHIELD CLIPS (SN)	NOT NECESSARY	\$50.00	\$0.00
1	SET ROCKER GARNISH RH CLIPS (SN)	NOT NECESSARY	\$60.00	\$0.00
			\$992.00	\$600.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RESET SYSTEM AFTER REPAIR WORKS	NOT NECESSARY	\$400.00	\$0.00
	TO REMOVE, CHANGE FRONT SUSPENSIO PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION	NOT NECESSARY	\$300.00	\$0.00
	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM		\$100.00	\$80.00
	TO TRANSFER DOOR GLASS, REGULATOR GEAR, MOTOR, RAILING, CHANNEL, TRIM BOARD, MECHANISM LOCK AND HANDLE		\$80.00	\$60.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODTPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT		\$1,000.00	\$600.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT		\$800.00	\$400.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL		\$120.00	\$80.00
			\$2,800.00	\$1,220.00
GRAND TOTAL			\$9,125.40	\$4,798.10
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$3,800.00
Report Ref No: CS/INC24110374/Aqh3e2				

TOTAL FOR SPARE PARTS: \$ 6,325.40 \$ 3,578.10
TOTAL FOR LABOUR : \$ 2,800.00 \$ 1,220.00
TOTAL REPAIR COST: \$ 9,125.40 \$ 4,798.10

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.