



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: YEE PEI LI

Ref: CS/INC24110378/Aqh3e2(N)

Date: 20/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLP 5339P	Veh. Inspected	SMX 1046G
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1304317-002	Excess (\$)	0.00
Assign From	JURAIDAH ABBAS	Assign Date	19/11/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA YARIS CROSS	c.c	1490
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	JTDKBAB3X0L002840	Colour	SILVER
Odometer	101567 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R16	DUNLOP	6 mm
L/H Front Tyre	205/65 R16	DUNLOP	6 mm
R/H Rear Tyre	205/65 R16	DUNLOP	6 mm
L/H Rear Tyre	205/65 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/11/2024	Inspect Date / Time	19/11/2024 (03:08 PM)
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**