

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120**Our File No:** CS/AIG24110379/EQP3E2**Date:** 04/03/2025REFERENCE

Insured/Claimant:	LEW KUEY HIONG	Policy No:	7240107094	
Date of Loss:	17/11/2024	Nature of Claim:	OD	Claim No: 5082903226SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMS160S</b>		
Make & Model:	AUDI Q4, SPORTBACK 45 E-TRON (A)	Engine No:	HIDDEN
Reg. Date:	27/06/2024 (Man. Year: 2024)	Chassis No:	WAUZZZFZ2RP072097
Colour:	White	Odometer:	3178 km
Engine Capacity:	0 cc		
Market Value/New Car Price:	S\$260,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/50 R19	Rear Tyre Size:	255/50 R19
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,697.00	2,455.92	6,241.08	71.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,632.00	2,132.00	4,500.00	67.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>15,329.00</b>	<b>4,587.92</b>	<b>10,741.08</b>	<b>70.07</b>
<b>- Excess (\$\$)</b>	1,200.00	1,200.00	0.00	0.00
<b>(\$\$)</b>	14,129.00	3,387.92	10,741.08	76.02
<b>+ GST 9.00/9.00% (\$\$)</b>	1,271.61	304.91	966.70	76.02
<b>Nett Amount (\$\$)</b>	<b>15,400.61</b>	<b>3,692.83</b>	<b>11,707.78</b>	<b>76.02</b>

INSPECTION

Date of Assignment:	19/11/2024	
Date Inspected:	20/11/2024	Inspected At: 24 Benoi Sector Repairer: Premium Automobiles Pte Ltd
Estimated Period of Repair:	3.0 days	

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER - UPPER	Not Necessary	1,178.00 FS	*- FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	204.00 FS	*- FS
3	1		*REAR BUMPER TRIM - SATIN BLACK	Not Necessary	264.00 FS	*- FS
4	1		*REAR BUMPER - LOWER	Not Necessary	956.00 FS	*- FS
5	1		*REAR BUMPER SPOILER - SELENITE SILVER	Missing	307.00 FS	*245.60 FS
6	1		*REAR SPOILER TOWING COVER - SELETINE SILVER	Not Necessary	62.00 FS	*- FS
7	1		*REAR BUMPER CABLE HOLDER	Not Necessary	13.00 FS	*- FS
8	4		*REAR BUMPER SECURING STRIP	Missing	106.00 FS	*84.80 FS
9	2		*REAR BUMPER SECURING STRIP	Missing	53.00 FS	*42.40 FS
10	2		*REAR BUMPER DAMPING	Not Necessary	53.00 FS	*- FS
11	1		*REAR CONTROL UNIT RETAINER	Missing	54.00 FS	*42.72 FS
12	1		*REAR LID OPENING CONTROL UNIT	Cut	554.00 FS	*443.20 FS
13	1		*REAR LID OPENING SENSOR LINE	Cut	244.00 FS	*194.80 FS
14	1		*AERIAL FOR (KESSY)	Not Necessary	84.00 FS	*- FS
15	2		*REAR PARKING AIR SENSOR	Not Necessary	572.00 FS	*- FS
16	4		*REAR PARKING AIR SENSOR SEAL RING	Not Necessary	57.00 FS	*- FS
17	1		*SET REAR BUMPER WIRING	Torn	277.00 FS	*221.60 FS
18	1		*REAR REINFORCEMENT BEAM	Not Necessary	1,248.00 FS	*- FS
19	1		*REAR BUMPER GUIDE SECTION - CENTER	Not Necessary	96.00 FS	*- FS
20	2		*REAR BUMPER GUIDE PROFILE - LH / RH	Not Necessary	132.00 FS	*- FS
21	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	206.00 FS	*- FS
22	2		*REAR WHEEL ARCH COVER - LH / RH	Necessary	1,284.00 FS	*1,026.40 FS
23	1		*REAR UNDERBODY TRIM	Broken	193.00 FS	*154.40 FS
24	1		*SUNDRIES	Not Necessary	500.00 FS	*- FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	8,697.00	2,455.92
--------------------	----------	----------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	2,000.00	600.00
3	TO RESPRAY REAR UPPER BUMPER, REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS	New	3,500.00	400.00
4	TO DE-ENERGEISING HIGH VOLTAGE SYSTEM, DEACTIVATION AND ACTIVATION	New	480.00	480.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
<b>Gross Labour Cost (S\$)</b>			<b>6,632.00</b>	<b>2,132.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >