

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24060282/KVP3M4  
Date: 29/07/2024

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002298301
Claimant Vehicle No :	SNL8659T	Insured Vehicle No :	SNC4688H
Date of Loss:	26/06/2024	Nature of Claim:	TP
		Claim No:	364646

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNL8659T	Engine No:	27091031524693
Make & Model:	MERCEDES-BENZ GLA200, 1.6 AMG (A)	Chassis No:	WDC1569432J469785
Reg. Date:	14/05/2018 (Man. Year: 2017)	Odometer:	102663 km
Colour:	Metallic Black		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/45R19	Rear Tyre Size:	235/45R19
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,398.21	7,053.31	5,344.90	43.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,150.00	1,370.00	1,780.00	56.51
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,548.21	8,423.31	7,124.90	45.82
Approved Total (Overridden) (S\$)		6,750.00		
(S\$)	15,548.21	6,750.00	8,798.21	56.59
+ GST 9.00/9.00% (S\$)	1,399.34	607.50	791.84	56.59
Nett Amount (S\$)	16,947.55	7,357.50	9,590.05	56.59

INSPECTION

Date of Assignment:	27/06/2024		
Date Inspected:	28/06/2024	Inspected At:	E M SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722
Estimated Period of Repair:	5.0 days		

Adjuster: KENNETH KONG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 29 Jul 2024)
<b>Parts:</b>	M1-SUV	MERCEDES-BENZ GLA200 1.6 AMG (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SNL8659T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR RH	Bent	2,176.46 FL	*2,176.46 FL
2	1		*REAR DOOR RH	Dented/Warped	2,344.87 FL	*2,274.37 FL
3	1		*REAR WHEEL ARCH PROTECTOR RH	Cut	270.76 FL	*270.76 FL
4	1		*REAR BUMPER	Serviceable	1,804.33 FL	*- FL
5	1		*PDC SENSOR RH	Serviceable	298.00 FL	*- FL
6	1		*SKIRT ROCKER CHROME SKIRTING RH	Serviceable	1,508.00 FL	*- FL
7	1		*REAR SPORT RIM RH	Dented	1,633.61 FL	*1,205.00 FL
8	1		*REAR WHEEL BEARING RH	Necessary	407.76 FL	*344.00 FL
9	1		*REAR SHOCK ABSORBER RH	Serviceable	632.00 FL	*- FL
10	1		*REAR LOWER ARM RH	Serviceable	504.00 FL	*- FL
11	1		*REAR KNUCKLE ARM RH	Bent	1,292.00 FL	*1,200.00 FL
12	1		*FRT DOOR WEATHERSTRIP RH (50%) (SN)	Necessary	329.78 FN	*164.89 F
13	1		*REAR DOOR WEATHERSTRIP RH (50%) (SN)	Necessary	329.78 FN	*164.89 F
14	1		*FRT DOOR INNER SEALER RH	Not Necessary	80.00 FS	*- FS
15	1		*REAR DOOR INNER SEALER RH	Not Necessary	80.00 FS	*- FS
16	1		*SET REAR BUMPER CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

<b>Sub Total (\$\$)</b>	<b>13,751.35</b>	<b>7,800.37</b>
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,287.18	747.06
- Nett Item Discount on N Items 10.00/0.00% (\$\$)	65.96	0.00
<b>Total Parts (\$\$)</b>	<b>12,398.21</b>	<b>7,053.31</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS	New	80.00	20.00
2	TO REMOVE & TRANSFER FRONT DOOR COMPONENTS	New	150.00	60.00
3	TO REMOVE & TRANSFER REAR DOOR COMPONENTS	New	150.00	60.00
4	TO REMOVE, REPAIR & REPLACE DAMAGED BODYPARTS, REALIGN BODYWORK AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	450.00
5	TO REMOVE, REPLACE REAR UNDERCARRIAGE PARTS	New	350.00	60.00
6	TO REMOVE, REINSTALL REVERSE SENSOR	New	100.00	0.00
7	TO RESET WHEEL ALIGNMENT	New	100.00	60.00
8	PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS	New	1,000.00	660.00
9	TO REMOVE & RENEW PDC SENSOR	New	100.00	0.00
10	RUST PROOFING ON AFFECTED PORTIONS	New	120.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,150.00</b>	<b>1,370.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >