

ASS. REC. BY:

REF:

MSG

CS/MSG24060282/Kvp3m4

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

EM

of

Insured: SNC 4688H

Policy No. 1002298301

Claims No. 364646

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

892K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SNC 86597

Yr Regn: 05.18

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M/ KIA 200

c.c. 1595

Colour

M. Black

A/C: Insured / Std / NI / NA

Sp. Reading

102883

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDC 1589432J 469785

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

R:

235/45R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

20/6/24

D.O.I.

28/6/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

C/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 GIA & EM not ready

317 67Rup @ 67501: Calw (red 8798.22, 56%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I: (\$

TOTAL

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	611G
Vehicle Details	
Vehicle No.:	SNL8659T
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Jun 2024
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	GLA200 AMG AUTO
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	27091031524693
Chassis No.:	WDC1569432J469785
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$34,997.00
Original Registration Date:	14 May 2018
First Registration Date:	14 May 2018
Transfer Count:	1
Actual ARF Paid:	\$40,996.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 May 2028
PARF Rebate Amount:	\$26,647.00
Intended COE Rebate Details	
COE Expiry Date:	13 May 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$39,000.00
COE Rebate Amount:	\$15,107.00
Total Rebate Amount:	\$41,754.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 27 Jun 2024

OK

E M Solution Pte Ltd

160 Sin Ming Drive #03-19, Sin Ming Autocity
Singapore 575722
Tel: 64560226

GST/Reg. No: 201016308K

Not Notified

1/1/24

Resurvey After Claim

5 days

ESTIMATE

Date : 27th June 2024

Mr **Teo Buck Seng**
Blk 431B Northshore Drive #21-800
Singapore 822431

Veh No : **SNL 8659T**
Make/Model : **Mercedes GLA200**
Chassis No : WDC1569432J469785
Date of Acc : 26.06.24
TP Veh No : SNC 4688H

S/No	Qty	Description	Unit Price	Amount
Materials				
1	1 pc	Frt Door RH <i>RM ✓</i>		
2	1 pc	Frt Door Weatherstrip RH <i>506.00 - RM</i>		
3	1 pc	Rear Door RH <i>nd/way ✓</i>		
4	1 pc	Rear Door Weatherstrip RH <i>RM 506.00</i>		
5	1 pc	Rear Wheel Arch Protector RH <i>RM</i>		
6	1 pc	Rear Bumper <i>RM X</i>		
7	1 pc	PDC Sensor RH <i>RM X</i>		
8	1 pc	Skirt Rocker Chrome Skirting RH <i>RM X</i>		
9	1 pc	Rear Sport Rim RH <i>nd ✓</i>		
10	1 pc	Rear Wheel Bearing RH <i>?</i>		
11	1 PC	Rear Shock Absorber RH <i>?</i>		
12	1 pc	Rear Lower Arm RH <i>?</i>		
13	1 pc	Rear Knuckle Arm RH <i>?</i>		

Less 10% : \$ -
Parts Total : \$ -

Special Nett		
1	1 pc	Frt Door Inner Sealer RH
2	1 pc	Rear Door Inner Sealer RH
3	1 set	Rear Bumper Clips

\$ *RM* 80.00 X
\$ *RM* 80.00 X
\$ *RM* 60.00 X
Special Nett : \$ 220.00

Labour	
1	To remove & rearrange electrical wirings, check lightings
2	To remove & transfer front door components.
3	To remove & transfer rear door components.
4	To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident.
5	To remove, replace rear undercarriage parts
6	To remove, instal reverse sensor
7	To reset wheel alignment
8	Putty and respray painting on affected portions.
9	To remove & renew PDC sensor
10	Rust proofing on affected portions.

\$ 80.00 *2d*
\$ 150.00 *60h*
\$ 150.00 *60h*
\$ 1,000.00 *40d*
\$ 350.00 *?*
\$ *RM* 100.00 X
\$ 100.00 *60h*
\$ 1,000.00 *60d*
\$ *RM* 100.00 X
\$ *RM* 120.00 X

Labour Total : \$ 3,150.00

for E M Solution Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Total Parts & Labour :

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.

Acknowledged by Repairer

Signature:

Date:

EM Solution Pte Ltd

160 Sin Ming Drive #03-19, Sin Ming Autocity
Singapore 575722
Tel: 64560226
GST/Reg. No: 201016308K

Not Authorised
L1 Rep & 6780h
Penny After Pain

ESTIMATE

Date : 27th June 2024

Mr **Teo Buck Seng**
Blk 431B Northshore Drive #21-800
Singapore 822431

Veh No : **SNL 8659T**
Make/Model : **Mercedes GLA200**
Chassis No : **WDC1569432J469785**
Date of Acc : **26.06.24**
TP Veh No : **SNC 4688H**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

S/No	Qty	Description	Unit Price	Amount
Materials				
1	1 pc	Frt Door RH	164.895m	\$ 2,176.46 ✓
2	1 pc	Frt Door Weatherstrip RH	na	\$ 329.78 502m
3	1 pc	Rear Door RH	2274.37	\$ 2,344.87 ✓
4	1 pc	Rear Door Weatherstrip RH	164.895m	\$ 329.78 502m
5	1 pc	Rear Wheel Arch Protector RH	na	\$ 270.76 ✓
6	1 pc	Rear Bumper	na	\$ 1,804.33 X
7	1 pc	PDC Sensor RH	na	\$ 298.00 X
8	1 pc	Skirt Rocker Chrome Skirting RH	na	\$ 1,508.00 X
9	1 pc	Rear Sport Rim RH	1205	\$ 1,633.61 ✓
10	1 pc	Rear Wheel Bearing RH	344	\$ 407.76 ✓
11	1 PC	Rear Shock Absorber RH	na	\$ 632.00 X
12	1 pc	Rear Lower Arm RH	na	\$ 504.00 X
13	1 pc	Rear Knuckle Arm RH	1200	\$ 1,292.00 ✓
				\$ 13,531.35
			Less 10%	\$ 1,353.14
			Parts Total :	\$ 12,178.22
Special Nett				
1	1 pc	Frt Door Inner Sealer RH	na	\$ 80.00 X
2	1 pc	Rear Door Inner Sealer RH	na	\$ 80.00 X
3	1 set	Rear Bumper Clips	na	\$ 60.00 X
			Special Nett :	\$ 220.00
Labour				
1		To remove & rearrange electrical wirings, check lightings	\$	80.00 20h
2		To remove & transfer front door components.	\$	150.00 60h
3		To remove & transfer rear door components.	\$	150.00 60h
4		To remove, repair & replace damaged bodyparts, realign bodywork and where consistent to the accident.	\$	1,000.00 4.50h
5		To remove, replace rear undercarriage parts	\$	350.00 60h
6		To remove, instal reverse sensor	\$	100.00 X
7		To reset wheel alignment	\$	100.00 60h
8		Putty and respray painting on affected portions.	\$	1,000.00 6.50h
9		To remove & renew PDC sensor	\$	100.00 X
10		Rust proofing on affected portions.	\$	120.00 X
			Labour Total :	\$ 3,150.00
			Total Parts & Labour :	\$ 15,548.22

for EM Solution Pte Ltd

Note: Parts quoted were based on visual inspection. Should additional parts be found damaged upon dismantling, we will seek your approval before proceeding.