

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMK 416Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR SLIDING DOOR O/S	DENTED/BENT	4,550.00	4,031.00
1	REAR SLIDING DOOR FRAME STICKER O/S	NECESSARY	100.00	80.00
1	REAR SLIDING DOOR INNER RUBBER O/S	NOT NECESSARY	220.00	-
1	REAR FENDER O/S	TO REPAIR SEE LABOUR	3,800.00	-
	LESS 10% DISCOUNT		-867.00	-411.10
			7,803.00	3,699.90
	SPECIAL NETT ITEMS			
1	SET REAR DOOR WRAP STICKER O/S (SN)	NECESSARY	600.00	400.00
1	SET REAR FENDER WRAP STICKER O/S (SN)	NECESSARY	600.00	400.00
			1,200.00	800.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACED REVERSE SENSOR.	NOT NECESSARY	80.00	-
	TO DISMANTLE & REFIX REAR FENDER GLASS O/S.	NOT NECESSARY	150.00	-
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.	NOT NECESSARY	120.00	-
	TO SPRAY RUST PROOFING.		80.00	30.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER O/S.		900.00	400.00
	TO PUTTY & SPRAY PAINTING.		680.00	500.00
			2,060.00	950.00
	GRAND TOTAL		11,063.00	5,449.90
	RECOMMENDED COST OF LUMP SUM REPAIRS			4,300.00

(TO ITS PRE-ACCIDENT CONDITION)

Report Ref No. CS/INC24110388/Uqh3m4(N)

TOTAL FOR SPARE PARTS: \$ 9,003.00 \$ 4,499.90 TOTAL FOR LABOUR: \$ 2,060.00 \$ 950.00 TOTAL REPAIR COST: \$11,063.00 \$ 5,449.90

(CONFIRMED)

CHUA KANG SENG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser