



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: JULIE

Ref: CS/INC24110388/Uqh3m4(N)

Date: 09/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLH 7278K	Veh. Inspected	SMK 416Y
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1304453-002	Excess (\$)	0.00
Assign From	JURAIDAH BINTE ABBAS	Assign Date	19/11/2024

2. Vehicle Particulars & Condition

Make & Model	MAXUS MIFA 9	c.c	0
Engine No.	HIDDEN	Year of Reg.	2023
Chassis No.	LSKG48L17PD053796	Colour	WHITE
Odometer	18434 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/50R19	CONTINENTAL	6 mm
L/H Front Tyre	255/50R19	CONTINENTAL	6 mm
R/H Rear Tyre	255/50R19	CONTINENTAL	6 mm
L/H Rear Tyre	255/50R19	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/11/2024	Inspect Date / Time	20/11/2024 (11:12 AM)
Survey held at	LEANG AUTOMOTIVE BLK 1 KAKI BUKIT AVE 6 #01-68 AUTOBAY@ KAKI BUKIT SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------