

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBS 5331M

	REPLACEMENT OF PARTS						
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)			
1	AXLE WHEEL FRONT	CUT	\$57.00	\$57.00			
1	BAG WATERPROOF (ROCKBROS)	TORN	\$140.00	\$140.00			
1	SET BALANCER HANDLE	сит	\$140.00	\$140.00			
1	BALL ASSY STEERING CONE	NOT NECESSARY	\$16.00	\$0.00			
1	BAR HANDLE	BENT	\$107.00	\$107.00			
1	BOLT FOOTREST	NOT NECESSARY	\$9.00	\$0.00			
2	BOLT FOOTREST 1 @\$9.00	NOT NECESSARY	\$18.00	\$0.00			
1	BRACKET FOOTREST FRONT LH	DAMAGED	\$141.00	\$141.00			
1	BRACKET UNDER FORK	NOT NECESSARY	\$377.00	\$0.00			
1	COVER HEADLIGHT	DAMAGED	\$259.00	\$259.00			
1	COVER METER LOWER	сит	\$107.00	\$107.00			
1	FENDER REAR	NOT NECESSARY	\$200.00	\$0.00			
1	FOOTREST ASSY	MISSING	\$542.00	\$542.00			
1	FORK LH	TO REPAIR SEE LABOUR	\$916.00	\$0.00			
1	FORK RH	SERVICEABLE	\$916.00	\$0.00			
1	HEADLIGHT	CRACKED	\$518.00	\$518.00			
1	HOLDER LEVER LH	сит	\$36.00	\$36.00			
1	LEVER CLUTCH	сит	\$36.00	\$36.00			
1	METER ASSY	CUT	\$893.00	\$893.00			
1	MIRROR COMP	сит	\$107.00	\$107.00			
1	NUT SUSPENSION (GCRAFT)	DAMAGED	\$236.00	\$236.00			
1	OBU TYE B (12V) NEW (DAMAGED)	FOC	\$341.00	\$0.00			
1	PEDAL REAR	сит	\$90.00	\$90.00			
1	PLATE FOOTREST	BENT	\$17.00	\$17.00			
1	PLATE FOOTREST LH	MISSING	\$76.00	\$76.00			
1	RACE STEERING TOP BALL	NOT NECESSARY	\$20.00	\$0.00			
1	RIM FRONT	TO REPAIR SEE LABOUR	\$893.00	\$0.00			
1	RUBBER COVER FOR CLUTCH LEVER	NOT NECESSARY	\$29.00	\$0.00			
1	RUBBER GEAR PEDAL	сит	\$6.00	\$6.00			
1	RUBBER, MAIN STEP	NECESSARY	\$29.00	\$29.00			



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

REPLACEMENT OF PARTS						
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	SEAT COMP SINGLE	TORN	\$423.00	\$423.00		
1	SIGNAL REAR LH	CUT	\$189.00	\$189.00		
1	SET SLIDER ENGINE	CUT	\$434.00	\$434.00		
1	STAND SIDE	CUT	\$67.00	\$67.00		
1	STEERING RACE	NOT NECESSARY	\$51.00	\$0.00		
1	VALVE RIM	NOT NECESSARY	\$25.00	\$0.00		
1	WEIGHT A, HANDLE	NOT NECESSARY	\$43.00	\$0.00		
1	PROTECTOR, R.COVER (ADDITIONAL)	NOT NECESSARY	\$44.00	\$0.00		
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$465.00)		
			\$8,548.00	\$4,185.00		
Special Nett						
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
1	OIL ENGINE (MOBIL) SUPER MOTO SYN TEC 10W/40 (SN) (ADDITIONAL)	NECESSARY	\$14.00	\$14.00		
			\$14.00	\$14.00		
Labour						
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)		
	LABOUR - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS. INCLUSIVE OF THE REPAIR OF FORK LH AND RIM FRONT		\$595.00	\$480.00		
	TRANSPORT CHARGES - ONE WAY TOWING		\$62.00	\$35.00		
	REPAIR BRACKET UNDER FORK (ADDITIONAL)	NOT NECESSARY	\$140.00	\$0.00		
	REPAIR FORK LH (ADDITIONAL)		\$125.00	\$80.00		
			\$922.00	\$595.00		
GRAND TOTAL			\$9,484.00	\$4,794.00		
	RECOMMENDED COST OF REPAIR SUM		\$4,300.00			
Report Ref No: CS/FCI24060283/Unh3e2						

NOTE: NEW PARTS REPLACEMENT

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.