

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internatio			
MS	MS FIRST CAPITAL		Ref:	CS3/FCI24110392/Tqp3e2	
	16 RAFFLES QUAY #42-01 HONG LEON		Date:	17/12/2024	
	SINGAPORE 04858		Code:	FCI2	
1.	ΈΥ				
	Insured Veh.	SHA 7792B	Veh. Inspected	SNS 6064K	
	Policy No.	D-24101861MFCT	Coverage	0	
	Claim No.	D24010140MFCT	Excess	\$0.00	
	Assign From	SWEE KEONG	Assign Date	19/11/2024	
2.		Vehic	le Details		
	Make & Model	TOYOTA LEXUS ES300H	C.C	2487	
	Engine No.	A25A5132642	Year of Reg.	06/03/2019	
	Chassis No.	JTHB21B12020303330	Colour	BLUE	
	Odometer	183499 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	235/45 R18	DUNLOP	6	
	L/H Front Tyre	235/45 R18	DUNLOP	6	
	R/H Rear Tyre	235/45 R18	DUNLOP	6	
	L/H Rear Tyre	235/45 R18	DUNLOP	6	
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.					
5.	General Information				
	Accident Date	17/11/2024	Inspection Date	20/11/2024 (12:00)	
	Survey held at	SEAH MOTOR TRADING CO LLP 60 JALAN LAM HUAT #07-60 CARROS CENTRE SINGAPORE 737869			
5a. Remarks					
	HE REPAIR ESTIMA	AS CONDUCTED ON A "WITHOUT F TE WAS NOT PRESENTED AT THE DLD TO PREPARE THE ESTIMATE. FIND DAMAGED VEHICLE PHOTO	TIME OF INSPECTION	DN.	
THE C) E D)M	ARKET VALUE:\$125		ICLE IS IN THE REG	ION OF \$4,000-\$5,000	
THE C) E D)M	ARKET VALUE:\$125	,000.00 (EST) AIR COST OF THE DAMAGED VEH	ICLE IS IN THE REG	ION OF \$4,000-\$5,000	

MTH

MOHAMAD TAUFIKH