

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24110395/KVP3M4**Date:** 02/12/2024REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1001963984
Claimant Vehicle No :	SNK3028C	Insured Vehicle No :	SLM4910L
Date of Loss:	16/11/2024	Nature of Claim:	TP
		Claim No:	380890

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNK3028C	Engine No:	27091030698751
Make & Model:	MERCEDES-BENZ A180 R17, 1.6 (A)	Chassis No:	WDD1760422J384793
Reg. Date:	14/08/2015 (Man. Year: 2015)	Odometer:	69882 km
Colour:	Metallic Silver		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 ZR18	Rear Tyre Size:	225/40 ZR18
Front Left Side:	Toyo 7 mm	Rear Left Side:	Toyo 7 mm
Front Right Side:	Toyo 7 mm	Rear Right Side:	Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,216.20	3,056.40	3,159.80	50.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,290.00	1,175.00	1,115.00	48.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,506.20	4,231.40	4,274.80	50.26
Approved Total (Overridden) (S\$)		3,350.00		
(S\$)	8,506.20	3,350.00	5,156.20	60.62
+ GST 9.00/9.00% (S\$)	765.56	301.50	464.06	60.62
Nett Amount (S\$)	9,271.76	3,651.50	5,620.26	60.62

INSPECTION

Date of Assignment:	21/11/2024		
Date Inspected:	19/11/2024	Inspected At:	THIAM HENG HUAT PTE LTD (SIN MING) 176 SIN MING DRIVE, #05-14 SINGAPORE 575721
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 02 Dec 2024)
Parts:	144	MERCEDES-BENZ A180 R17 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNK3028C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE EMBLEM	Necessary	80.00 F	*80.00 FL
2	1		*TAILGATE ASSY	Repair	1,645.00 F	*- FL
3	1		*REAR BUMPER	Buckled	1,409.00 F	*1,409.00 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	568.00 F	*568.00 FL
5	1		*REAR BUMPER INNER BRACKET	Cracked	135.00 F	*135.00 FL
6	1		*REAR BUMPER LOWER GARNISH	Dented/Mtg Cracked	485.00 F	*485.00 FL
7	1		*REAR BUMPER LOWER GARNISH MLDG	Dented	186.00 F	*186.00 FL
8	1		*REAR BUMPER INNERGARNISH	Cracked	208.00 F	*208.00 FL
9	1		*REAR END PANEL	Repair	990.10 F	*- FL
10	1		*REAR END PANEL TOP GARNISH	Serviceable	185.10 F	*- FL
11	1		*REAR EXHAUST CHROME COVER LH	Dented	325.00 F	*325.00 FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	6,216.20 3,396.00
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 339.60
					Total Parts (\$\$)	6,216.20 3,056.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND REFIT DAMAGED PARTS	New	900.00	600.00
2	TO SPRAY PAINT ON AFFECTED PARTS	New	1,000.00	450.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	120.00	60.00
4	TO REMOVE AND REFIT REAR GARNISHES	New	120.00	50.00
5	TUFF COAT ON AFFECTED PARTS	New	100.00	0.00
6	TO CHECK WIRING	New	50.00	15.00
Gross Labour Cost (\$\$)			2,290.00	1,175.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >