



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLC 8004D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	1,200.00	1,200.00
2	FRONT BUMPER BRACKET - LH & RH	NOT NECESSARY	92.00	-
2	FRONT BUMPER SIDE RETAINER - LH & RH	NOT NECESSARY	35.00	-
1	FRONT BUMPER CHROME MOULDING - RH	CUT	180.00	70.00
1	FOG LAMP - RH	NOT NECESSARY	760.00	-
1	FRONT FENDER - RH	NOT NECESSARY	385.00	-
1	HEADLAMP - RH	CUT	4,100.00	3,259.00
1	HEADLAMP PANEL - RH	NOT NECESSARY	150.00	-
	LESS 20% DISCOUNT		-1,380.40	-905.80
			5,521.60	3,623.20
	<u>LABOUR</u>			
	TO KNOCKING & PULL OUT FRONT PORTION & RENEW ABOVE PARTS.		600.00	300.00
	TO PUTTY & SPRAY UP PAINT WORKS.		500.00	200.00
	TO CHECK WIRING SYSTEM.		20.00	20.00
	TO UNDERSEAL.	NOT NECESSARY	30.00	-
			1,150.00	520.00
	GRAND TOTAL		6,671.60	4,143.20
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			3,100.00

Report Ref No. CS/AGI24110398/Avp3e2(N)

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.