

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Mobile: 9061 0543 Email: mirage1195@gmail.com

ACCIDENT VEHICLE INSPECTION REPORT

Report no	: 385M1024.SLA
Vehicle no	: XE891J

1 REFERENCE

Date of inspection	: 7 October 2024
Requested by	: Octogon Logistics Pte Ltd c/o 2A Kian Teck Avenue Singapore 628896
Type of survey	: Independent
Repairer	: Soon Lee Auto Trading 2A Kian Teck Avenue, Singapore 628896
Date of accident	: 16 September 2024

2 VEHICLE DATA

Make/model	: SCANIA P400LA4X2MSZ
Chassis no	: YS2P4X20005392368
Engine no	: 6886534
Date of registration	: 30 July 2015
Engine capacity	: 12742 cc
Odometer reading	: 369175.7 km
Colour	: White

3 STATIC CONDITION CHECK

Steering	: In order
Foot brakes	: In order
Hand brakes	: In order
Paintwork	: Good
General Condition	: Good

4 TIRE CONDITION CHECK

	<u>RH/MAKE</u>	<u>LH/MAKE</u>	<u>SIZE</u>
Front tread	: 10 mm/Firenza	10 mm/Firenza	315/80R22.5
Rear tread	: 10 mm/Firenza	10 mm/Firenza	315/80R22.5

5 BRIEF DESCRIPTION OF DAMAGE

Front windscreen glass cracked, front firewall panel bent, LH front bumper side dented/bent/distorted, radiator grille bent, RH & centre bumper grazed, LH headlamp broken, front bonnet dented/bent/distorted, etc. Please see para. 8 of this report for more details.

6 REMARKS

This inspection is carried out on a "WITHOUT PREJUDICE" basis and we have not authorized any repairs.

7 RECOMMENDATION

Cost of repairs	: <u>\$21,000.00</u> (lump sum)
No. of days taken	: <u>Nine (9)</u>

8 ASSESSMENT OF DAMAGE AND COSTS

Report no: 385M1024.SLA
Vehicle no: XE891J

A SPARE PARTS

Description	Qty	Assessed Condition	Repairer's Amount	Revised Amount	
Front windscreen glass	1	cracked	3,800.90	3,800.90	/
Front windscreen glass top garnish (black)	1	side broken	488.10	488.10	/
Front windscreen glass lower garnish (black) LH/RH	2	cracked	2,440.30	2,440.30	450 /
Front windscreen glass lower centre garnish (black)	1	broken	201.30	201.30	/
Front firewall	1	to repair	7,550.30	0.00	
Front bonnet	1	dented/bent/distorted	4,800.80	4,800.80	/
Front bonnet suppoort sub- frame assy	1	bent/distorted	601.50	601.50	/
Front bonnet sub-frame damper (pair)	1	bent/stiffened	450.00	450.00	x nn
Front bonnet sub-frame stopper rubber	1	torn	56.10	56.10	x nn
Front bonnet 'SCANIA' logo	1	necessary	85.00	85.00	/
Front bonnet 'SCANIA' wording	1	necessary	120.00	120.00	/
Front bonnet lock assy	1	bent/distorted/cracked	221.00	221.00	/
Front bonnet lock release cable assy	1	end snapped	111.80	111.80	x nn
Front bonnet lock striker	1	bent/distorted	75.00	75.00	x nn
LH front corner panel	1	cable dented/torn	709.84	709.84	/
LH front corner panel vent cover (black)	1	bent/deformed	254.10	254.10	/
RH front corner panel	1	leg broken/cracked	709.84	709.84	/
LH headlamp assy	1	broken	1,524.35	1,524.35	x nn
LH headlamp housing	1	corner bent/broken	558.60	558.60	x nn
LH side mirror	1	scraped	1,223.90	1,223.90	x nn
LH side blind spot mirror (round)	1	glass broken	96.10	96.10	/
LH side mirror arm	1	bent	295.10	295.10	x nn
Horn	1	broken	95.00	95.00	/
Cabin air cleaner assy	1	broken	2,667.50	2,667.50	/
Wiper linkage support frame	1	dented/bent/distorted	226.30	226.30	/
Wiper linkage c/motor assy	1	jammed	512.60	512.60	/
Front bumper side LH	1	dented/bent/distorted	755.20	755.20	x nn
Front bumper side side garnish LH	1	broken	101.00	101.00	x nn
Front bumper side RH	1	to repair	755.20	0.00	
Front bumper centre	1	to repair	555.60	0.00	
LH front signal lamp assy	1	grazed/leg broken	610.20	610.20	x nn
Front bonnet handle LH/RH	2	bent	250.00	250.00	
Front bonnet lower panel	1	broken	388.50	388.50	/
Radiator grille	1	to repair	2,580.60	0.00	
Radiator grille 'P360' emblem	1	necessary	80.00	80.00	x nn
Radiator grille support arm	1	bent/distorted	333.10	333.10	x nn
Radiator grille support arm side bracket LH	1	bent/distorted	76.20	76.20	x nn
Subtotal of the above			36,360.93	24,919.23	
Discount 10%			3,636.09	2,491.92	
(Special nett)	Subtotal 1:		32,724.84	22,427.31	
Front windscreen gum	1	necessary	160.00	160.00	120
ERP bracket	1	necessary	26.00	26.00	20
Air cleanser filter	1	squashed/deformed	105.00	105.00	x nn
Subtotal 2:			291.00	291.00	
Total cost of parts:			33,015.84	22,718.31	

Report no: 385M1024.SLA
Vehicle no: XE891J

B LABOUR

To remove and replace, to cut and weld, to panel beat and straighten damaged parts and body panels.	2,000.00	1,500.00	800
To putty and spray paint all affected parts and areas.	1,800.00	1,500.00	700
To apply anti-rust undercoating.	150.00	90.00	30
To remove and renew the damaged front windscreen glass and install the same.	350.00	250.00	200
To check wiring.	60.00	45.00	30
To refocus headlamp beams to specifications.	90.00	60.00	x
Total cost of labour:	4,450.00	3,445.00	
Total cost of repair:	37,465.84	26,163.31	

9 CONCLUSION

The revised or adjusted cost of repairs to restore the vehicle is \$26,163.31

(a) The recommended cost of repair based on lump sum repairs would be \$21,000.00


(b) The estimated number of days for the repairs would be Nine (9)
(1st Reinspection conducted on 8 October 2024)
(Post Repair Inspection conducted on 15 October 2024)

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.

Note: Lump Sum Repair Basis

This means the repairer is allowed to replace the damaged parts with used, reconditioned or new parts, or repair it to a roadworthy condition.

Prepared by:


.....
Liaw Leong San
Licensed Automotive Appraiser

Dated: 11 November 2024

6 days

PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189
Mobile: 9061 0543 Email: mirage1195@gmail.com

Octogon Logistics Pte Ltd
c/o 2A Kian Teck Avenue
Singapore 628896

INVOICE

Invoice no:	POS0385/24
Date:	11 November 2024
Report no:	385M1024.SLA
Vehicle :	XE891J

No	Item Description	Qty	Unit Price	Total Amount (\$)
01	Being charges for the inspection of the accident vehicle, transport and photographs.			1,688.00
SGD(\$): One Thousand Six Hundred and Eighty-eight only			Grand Total:	1,688.00

"Cheque should be crossed and made payable to "Pro-Option Services"

PRO-OPTION SERVICES

.....
Authorised Signature