

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG24060284/UVP3E2  
Date: 18/07/2024

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002967577		
<b>Claimant Vehicle No :</b>	SLX4119Y	<b>Insured Vehicle No :</b>	SBY13H		
Date of Loss:	26/06/2024	Nature of Claim:	TP	Claim No:	364641

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX4119Y	Engine No:	3A92UGX3144
Make & Model:	MITSUBISHI SPACE STAR, 1.2 CVT (A)	Chassis No:	MMCXTA03AJH021461
Reg. Date:	27/03/2018 (Man. Year: 2018)	Odometer:	75414 km
Colour:	Blue		
Engine Capacity:	1193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R15	Rear Tyre Size:	185/55 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,754.87	2,749.88	7,004.99	71.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,650.00	2,030.00	2,620.00	56.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,404.87	4,779.88	9,624.99	66.82
Approved Total (Overridden) (\$\$)		3,800.00		
Nett Amount (\$\$)	14,404.87	3,800.00	10,604.87	73.62

INSPECTION

Date of Assignment:	27/06/2024	Zoom Auto Werks - Kaki Bukit (HQ)
Date Inspected:	27/06/2024 Inspected At:	BLK 15 KAKI BUKIT ROAD 4, #01-53 BARTLEY BIZ CENTRE
Estimated Period of Repair:	5.0 days	Singapore 417808

Adjuster: MARCUS CHUA      Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 18 Jul 2024)
Parts:	144	MITSUBISHI SPACE STAR 1.2 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLX4119Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	No such part	78.00 FN	*- FN
2	1		*REAR TAILGATE	Badly Dented	1,339.65 FN	*764.00 FN
3	1		*REAR TAILGATE INNER LOCK	Damaged	200.64 FN	*145.00 FN
4	1		*REAR TAILGATE WEATHERSTRIP	Twisted	488.31 FN	*111.00 FN
5	1		*REAR TAILGATE LOGO	Necessary	111.31 FN	*60.00 FN
6	1		*REAR TAILGATE SPACE STAR EMBLEM	Necessary	90.97 FN	*48.00 FN
7	1		*REAR TAILGATE MIVEC EMBLEM	Necessary	89.89 FN	*48.00 FN
8	1		*REAR TAILGATE OUTER HANDLE	Not Necessary	245.00 FN	*- FN
9	2		*REAR TAILLAMPS	Not Necessary	1,376.66 FN	*- FN
10	1		*REAR END PANEL	Badly Dented	600.74 FN	*448.00 FN
11	1		*REAR END PANEL INNER TRIM	Twisted	122.31 FN	*122.31 FN
12	1		*REAR END KEYLESS SENSOR	Cracked	288.96 FN	*101.00 FN
13	2		*REAR FENDERS	Repair	2,435.30 FN	*- FN
14	2		*REAR FENDER INNER TRIMS	Not Necessary	977.92 FN	*- FN
15	1		*REAR BUMPER	Deformed / Torn	988.74 FN	*789.00 FN
16	2		*REAR BUMPER LOWER BRACKETS	Not Necessary	223.30 FN	*- FN
17	2		*REAR BUMPER REFLECTORS	Not Necessary	243.10 FN	*- FN
18	1		*REAR FLOOR PANEL TOP BOARD	Torn	197.50 FN	*162.00 FN
19	2		*REAR NUMBER PLATE LAMPS	Cracked / Twisted	96.00 FN	*96.00 FN
20	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
21	1		*REAR TAILGATE C&C EMBLEM	Necessary	40.00 FS	*40.00 FS
22	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
23	1		*REAR NUMBER PLATE	Damaged	50.00 FS	*35.00 FS
24	1		*SET REAR REVERSE SENSOR	Serviceable	350.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	10,774.30	3,039.31
- Nett Item Discount on N Items 10.00/10.00% (S\$)	1,019.43	289.43
Total Parts (S\$)	9,754.87	2,749.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE, REPLACED DAMAGED LAMP AND CHECK UP REAR WIRING	New	80.00	20.00
2	TO REMOVE AND REFIT INNER GARNISHES	New	180.00	60.00
3	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	180.00	30.00
4	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	80.00	50.00
5	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
6	TO APPLY UNDERCOATING	New	150.00	50.00
7	PANEL BEATING	New	2,000.00	800.00
8	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	1,800.00	900.00
<b>Gross Labour Cost (S\$)</b>			<b>4,650.00</b>	<b>2,030.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >