

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTECICS Limited
10 Eunos Road 8, #09-04A Singapore Post Centre
Singapore 408600**Our File No:** CS/ICS24110401/KNP3E2**Date:** 26/11/2024REFERENCE

Insured/Claimant:	TAN NGUAN KENG	Policy No:	MPC23A00383602	
Date of Loss:	16/11/2024	Nature of Claim:	OD	Claim No: DMPC2401573H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCF111X		
Make & Model:	BMW 520I, 2.0 AT D/AB 2WD 4DR LED NAV (A)	Engine No:	B4960872N20B20B
Reg. Date:	30/06/2015 (Man. Year: 2014)	Chassis No:	WBA5A32060D790590
Colour:	Metallic Black	Odometer:	81557 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	S\$35,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/35Z R20	Rear Tyre Size:	285/30Z R20
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	12,261.00	11,095.00	1,166.00	9.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,210.00	520.00	690.00	57.02
Paintwork Labour	880.00	500.00	380.00	43.18
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,351.00	12,115.00	2,236.00	15.58
Approved Total (Overridden) (S\$)		7,000.00		
- Excess (S\$)	0.00	1,250.00	-1,250.00	
(S\$)	14,351.00	5,750.00	8,601.00	59.93
+ GST 9.00/9.00% (S\$)	1,291.59	517.50	774.09	59.93
Nett Amount (S\$)	15,642.59	6,267.50	9,375.09	59.93

INSPECTION

Date of Assignment:	19/11/2024	Present Location:	Vin's Motor Pte Ltd (Sin Ming)
Date Inspected:	20/11/2024	Inspected At:	20 Sin Ming Lane, #06-65 MIDVIEW CITY Singapore 573968
Estimated Period of Repair:	4.0 days		

Adjuster: KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2024)
Parts:	143	BMW 520I 2.0 AT D/AB 2WD 4DR LED NAV (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SCF111X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*FRONT BONNET (WCP)	Bent	2,100.00 F	*2,100.00 F
2	1	NA	*BONNET RH HINGE (WCP)	Repair	150.00 F	*- F
3	1	NA	*BONNET LH HINGE (WCP)	Repair	150.00 F	*- F
4	1	NA	*BONNET RH LOWER LOCK (WCP)	Distorted	210.00 F	*210.00 F
5	1	NA	*LH GRILLE (WCP)	Dented	240.00 F	*240.00 F
6	1	NA	*RH GRILLE (WCP)	Dented	240.00 F	*240.00 F
7	1	NA	*RH HEADLAMP (WCP)	Broken	3,600.00 F	*3,600.00 F
8	1	NA	*RH HEADLAMP SUPPORT HOUSING (WCP)	Cracked	260.00 F	*260.00 F
9	1	NA	*RH HEADLAMP WASHER SPRAY (WCP)	Dented	160.00 F	*160.00 F
10	1	NA	*FRONT BUMPER (WCP)	Buckled	1,200.00 F	*1,200.00 F
11	1	NA	*FRONT BUMPER EMBLEM (WCP)	Necessary	90.00 F	*90.00 F
12	1	NA	*FRONT BUMPER TOWING COVER (WCP)	Serviceable	60.00 F	*- F
13	2	NA	*FRONT BUMPER PARKING SENSOR @ CENTER (WCP)	Shorted	400.00 F	*400.00 F
14	1	NA	*FRONT BUMPER CENTER LOWER GRILLE (WCP)	Cracked	140.00 F	*140.00 F
15	1	NA	*FRONT BUMPER RH FOG LAMP COVER (WCP)	Serviceable	90.00 F	*- F
16	1	NA	*FRONT BUMPER RH SIDE RETAINER (WCP)	Distorted	20.00 F	*20.00 F
17	1	NA	*FRONT BUMPER LH SIDE RETAINER (WCP)	Serviceable	20.00 F	*- F
18	1	NA	*FRONT BUMPER SPONGE (WCP)	Cracked	110.00 F	*110.00 F
19	1	NA	*FRONT BUMPER REINFORCEMENT (WCP)	Bent	650.00 F	*650.00 F
20	1	NA	*FRONT BUMPER LOWER BEAM (WCP)	Distorted	180.00 F	*180.00 F
21	1	NA	*FRONT BUMPER UNDER COVER (WCP)	Serviceable	330.00 F	*- F
22	10	NA	*FRONT BUMPER CLIPS (WCP)	Necessary	20.00 F	*20.00 F
23	1	NA	*FRONT SUPPORT PANEL (WCP)	Repair	260.00 F	*- F
24	1	NA	*RADIATOR AIR DUCT (WCP)	Cracked	430.00 F	*430.00 F
25	1	NA	*FRONT NO.PLATE (WCP)	Bent	40.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part. S=SpcNett.						
Sub Total (\$)					11,150.00	10,090.00
+ Margin on L,N Items 10.00/10.00% (\$)					1,111.00	1,005.00
Total Parts (\$)					12,261.00	11,095.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TO SPRAY PAINTING	New	880.00	500.00
<u>Labour Items</u>				
2	TO REFILL AIRCON GAS	New	150.00	0.00
3	TO RESET HEADLAMP SYSTEM	New	280.00	20.00
4	TO REPAIR DAMAGES	New	780.00	500.00
Gross Labour Cost (S\$)			2,090.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >