

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24110402/UUA3Q2**Date:** 14/01/2025REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100505998
Claimant Vehicle No :	SJQ7197L	Insured Vehicle No :	SDN3388R
Date of Loss:	19/11/2024	Nature of Claim:	TP
		Claim No:	8258120296SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJQ7197L	Engine No:	M16A1463023
Make & Model:	SUZUKI SX4, 1.6 HB (A)	Chassis No:	JSAGYA21S00205708
Reg. Date:	25/05/2009 (Man. Year: 2009)	Odometer:	241249 km
Colour:	White		
Engine Capacity:	1586 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,290.23	2,962.63	2,327.60	44.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,920.00	2,040.00	1,880.00	47.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,210.23	5,002.63	4,207.60	45.68
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	9,210.23	4,000.00	5,210.23	56.57
+ Car Rental (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		4,502.18		

INSPECTION

Date of Assignment:	20/11/2024		
Date Inspected:	20/11/2024	Inspected At:	Hup Motor Trading & Service (HQ) Blk 9004 Tampines Street 93, #01-120 Singapore 528838
Estimated Period of Repair:	4.0 days		

Adjuster: MARCUS CHUA**Manager:** NA MENG YAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Repair	1,299.90 FL	*- FL
2	1		*FRONT BONNET N/S HINGE	Not Necessary	67.60 FL	*- FL
3	1		*N/S HEAD LAMP ASSY	Cracked	784.60 FL	*784.60 FL
4	1		*N/S HEAD LAMP BRACKET	Not Necessary	38.00 FL	*- FL
5	1		*FRONT N/S FENDER	Bent	921.90 FL	*621.00 FL
6	1		*FRONT N/S FENDER INNER SHIELD	Torn	157.00 FL	*157.00 FL
7	8		*FRONT N/S FENDER INNER SHIELD CLIPS	Necessary	40.00 FL	*40.00 FL
8	1		*FRONT N/S FENDER WHEEL GUARD	Grazed	162.00 FL	*162.00 FL
9	10		*FRONT N/S FENDER WHEEL GUARD CLIPS	Not Necessary	50.00 FL	*- FL
10	1		*FRONT N/S FENDER VVT EMBLEM	Necessary	32.00 FL	*32.00 FL
11	1		*N/S HEAD LAMP PANEL	Bent / Twisted	182.00 FL	*182.00 FL
12	1		*FRONT BUMPER	Cut / Torn	863.40 FL	*790.45 FL
13	10		*FRONT BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
14	1		*FRONT BUMPER N/S SIDE RETAINER	Cracked	38.00 FL	*38.00 FL
15	1		*FRONT BUMPER REINFORCEMENT	Repair	279.00 FL	*- FL
16	1		*FRONT BUMPER N/S SIDE BRACKET CLIPS	Not Necessary	10.00 FL	*- FL
17	1		*FRONT BUMPER N/S FOG LAMP GARNISH	Grazed	99.10 FL	*99.10 FL
18	1		*FRONT BUMPER N/S SIDE GARNISH	Grazed	66.90 FL	*66.90 FL
19	1		*FRONT BUMPER CENTRE LOWER GARNISH	Cut / Twisted	175.00 FL	*175.00 FL
20	1		*FRONT BUMPER N/S FOG LAMP ASSY	Cracked	287.40 FL	*287.40 FL
21	1		*FRONT N/S SPORT RIM	Repair	620.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,223.80	3,485.45
- List Item Discount on L Items 15.00/15.00% (\$\$)	933.57	522.82
Total Parts (\$\$)	5,290.23	2,962.63

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO WIRING CHECK UP & ADJUST HEADLIGHT ALIGNMENT	New	50.00	30.00
2	TO CHECK & ADJUST FRONT WHEEL ALIGNMENT & BALANCING	New	150.00	60.00
3	TO RESPRAY TUFF KOTE ON ALL AFFECTED ACCIDENT PARTS	New	120.00	50.00
4	LABOUR CHARGE TO REMOVE & OUT OUT DAMAGED PARTS ,TO JACK STRAIGHTEN & KNOCKING OUT FRONT SUPPORT PANEL ,FRONT N/S DOOR & NECESSARY PARTS ,TO WELD ,RENEW & ALIGN ABOVE PARTS	New	1,800.00	800.00
5	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,800.00	1,100.00
Gross Labour Cost (\$\$)			3,920.00	2,040.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >