5/30/25, 11:58 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110405/TPA3Q2

30/05/2025 Date:

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D23MPC0003000_01

Claimant Vehicle SKL9300G Insured Vehicle No: PD1126D

No:

Date of Loss: 12/11/2024 Nature of Claim: TP Claim No: MFL2024D0013895

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKL9300G**

Make & Model: BMW 520I, 2.0 (A) Engine No: F077K298B48B20A Reg. Date: 26/03/2020 (Man. Year: 2019) WBAJR12090CD71685 Chassis No:

Colour: Black Odometer: 42461 km

Engine Capacity: 1998 cc Market Value/New Car N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Pre-accident Condition: Yes Engine Modification: No Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: 245/45 R18 Rear Tyre Size: 245/45 R18 Front Left Side: Pirelli 6 mm Pirelli 6 mm Rear Left Side: Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,931.75	2,426.40	4,505.35	65.00
Miscellaneous Items		0.00	0.00	0.00	
Labour		4,921.00	4,071.00	850.00	17.27
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	11,852.75	6,497.40	5,355.35	45.18
	+ GST 9.00/9.00% (S\$)	1,066.75	584.77	481.98	45.18
	Nett Amount (S\$)	12,919.50	7,082.17	5,837.33	45.18
	+ Loss of Use (6.0 x S	\$\$100.00/day) (S\$)	600.00		
	+ Do	c/Search Fee (S\$)	27.25		
		Nett Liability (S\$)	7,709.42		

INSPECTION

16/04/2025 Date of Assignment:

Performance Motors Limited (HQ) Inspected At: Date Inspected: 16/04/2025

303 Alexandra Road, Singapore

Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID Manager: **CHEW HSIAO TONG**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 09 May 2025)

Parts: 143 BMW 520I 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKL9300G)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

Qty Part No. Particulars	Condition	Repairer's	Amount
1 *SUNDRIES	Necessary	150.00 FS	*80.00 FS
1 *(S/L) LH PROTECTION FOIL	Not Necessary	14.70 FS	*- FS
1 *(S/L) RH PROTECTION FOIL	Not Necessary	14.70 FS	*- FS
1 *REAR BUMPER CARRIER	Not Necessary	633.60 FS	*-FS
1 *REAR BUMPER BOTTOM REINFORCEMENT	Cracked	160.55 FS	*160.55 FS
1 *REAR BUMPER CENTRE GUIDE	Cracked	194.30 FS	*194.30 FS
1 *REAR BUMPER TRIM STRIP	Cut	84.10 FS	*84.10 FS
1 *REAR BUMPER TOWING EYE FLAP PRIMED	Not Necessary	57.50 FS	*- FS
1 *REAR BUMPER PANEL PRIMED (PDC/PMA)	Deformed	1,771.75 FS	*1,771.75 FS
1 *SET MOUNTING PMA SENSOR	Not Necessary	75.55 FS	*- FS
1 *FRT LH GRILLE (M/SPORT)	Not Necessary	174.40 FS	*- FS
1 *FRT RH GRILLE (M/SPORT)	Not Necessary	174.40 FS	*-FS
1 *UNDERBODY PANELLING REAR	Deformed	52.70 FS	*52.70 FS
10 *DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	56.50 FS	*- FS
8 *PDC SENSOR SOPHISTOGRAU II WA90	Not Necessary	3,234.00 FS	*- FS
1 *FRONT EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
anchise part. S=SpcNett.	Total Parts (S\$)	6,931.75	2,426.40
anchise part. S=SpcNo	ett.		

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount	
Lab	<u>our Items</u>				
1	REPLACE REAR BUMPER INCLUDE ATTACHMENT ETC AND CARRYOUT REPAIRING WORK ON FRONT BUMPER AND ACCIDENT DAMAGE AREA		2,550.00	1,700.00	
2	PAINTING FRONT AND REAR BUMPER	New	2,076.00	2,076.00	
3	TO CHECK ELECTRICAL WIRING SYSTEM AT THE FRONT AND REAR SECTIONS FOR PROPER FUNCTION	New	295.00	295.00	
	Gross Labour Cost (S\$)		4,921.00	4,071.00	
	Report was unsubmitted during this print-out.				

< END OF ESTIMATES >