

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110406/UPA3Q2
Date: 07/02/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_05
Claimant Vehicle No : SKW9910M Insured Vehicle No : YP5951S
Date of Loss: 19/11/2024 Nature of Claim: TP Claim No: MFL2024D0013745

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKW9910M
Make & Model: NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A) Engine No: HRA2204158A
Reg. Date: 24/11/2015 (Man. Year: 2015) Chassis No: SJNFEAJ11U1518265
Colour: Red Odometer: 135523 km
Engine Capacity: 1197 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17 Rear Tyre Size: 215/60 R17
Front Left Side: Grenlander 6 mm Rear Left Side: Grenlander 6 mm
Front Right Side: Grenlander 6 mm Rear Right Side: Grenlander 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,406.00	7,996.36	6,409.64	44.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,160.00	1,870.00	290.00	13.43
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,566.00	9,866.36	6,699.64	40.44
Approved Total (Overridden) (S\$)		6,800.00		
(S\$)	16,566.00	6,800.00	9,766.00	58.95
+ GST 9.00/9.00% (S\$)	1,490.94	612.00	878.94	58.95
Nett Amount (S\$)	18,056.94	7,412.00	10,644.94	58.95
+ Car Rental (7.0 x S\$100.00/day + 9.00% GST) (S\$)		763.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		8,177.18		

INSPECTION

Date of Assignment: 20/11/2024
Date Inspected: 20/11/2024 Inspected At: Stytech Auto Pte Ltd (kaki Bukit) (HQ)
2 Kaki Bukit Ave 2, #01-03 Kaki Bukit Autohub
Singapore 417921
Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Dec 2024)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW9910M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Badly Dented	3,556.20 F	*3,408.50 FN
2	1		*REAR BOOT GLASS	Not Necessary	1,174.80 F	*- FN
3	1		*REAR BOOT WEATHERSTRIP	Twisted	151.20 F	*151.20 FN
4	1		*REAR BOOT GLASS SEALANT	Necessary	60.00 FS	*40.00 FS
5	1		*REAR BOOT WIPER ARM	Not Necessary	89.50 FS	*- FS
6	1		*REAR BOOT WIPER BLADE	Not Necessary	35.50 FS	*- FS
7	2		*REAR BOOT REFLECTOR LAMP (LEFT & RIGHT)	Cracked	772.00 F	*772.00 FN
8	1		*REAR BOOT CENTER GARNISH	Cracked	428.90 F	*305.20 FN
9	1		*REAR BOOT CENTER GARNISH EMBLEM	Necessary	79.90 F	*79.90 FN
10	2		*REAR BOOT LICENCE PLATE LAMP (LEFT & RIGHT)	Not Necessary	176.20 F	*- FN
11	1		*REAR BOOT CAMERA	Serviceable	250.00 FS	*- FS
12	1		*REAR BOOT QASHQAI WORDING	Necessary	115.10 F	*115.10 FN
13	1		*REAR BOOT LICENCE PLATE	Damaged	40.00 FS	*40.00 FS
14	1		*REAR BOOT LOCK	Twisted	248.70 F	*248.70 FN
15	1		*REAR BOOT INNER TRIM BOARD	Serviceable	420.50 F	*- FN
16	1		*REAR BOOT INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS
17	1		*REAR BOOT INNER MACHANISM LOCK	Repeated	232.80 F	*- FN
18	1		*REAR BOOT WIPER MOTOR	Not Necessary	534.20 F	*- FN
19	1		*TAILLAMP (LEFT & RIGHT)	N/S Cracked	901.00 F	*450.50 FN
20	1		*REAR BUMPER	Distorted	996.50 F	*975.80 FN
21	1		*REAR BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
22	4		*REAR BUMPER REVERSE SENSOR	Malfunction	250.00 FS	*200.00 FS
23	1		*REAR BUMPER REFLECTOR (LEFT & RIGHT)	N/S Cracked	173.00 F	*86.50 FN
24	1		*REAR BUMPER LOWER GARNISH	Not Necessary	305.20 F	*- FN
25	2		*REAR BUMPER RETAINER (LEFT & RIGHT)	Not Necessary	122.40 F	*- FN
26	1		*REAR FENDER ARCH MOULDING (LEFT & RIGHT)	N/S Torn	531.60 F	*265.80 FN
27	1		*REAR BUMPER SPONGE	Torn	198.10 F	*198.10 FN
28	1		*REAR REINFORCEMENT	Bent / Twisted	746.20 F	*746.20 FN
29	1		*REAR END PANEL	Dented / Bent	660.10 F	*591.60 FN
30	1		*REAR END PANEL TOP GARNISH	Twisted	145.30 F	*145.30 FN
31	1		*REAR END PANEL TOP GARNISH CHROME	Not Necessary	234.10 F	*- FN
32	1		*WHETHER STRIPE	Repeated	222.10 F	*- FN
33	1		*SPARE TYRE TRIM BOARD	Serviceable	494.90 F	*- FN

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (\$\$)	14,406.00	8,850.40
- Nett Item Discount on N Items 0.00/10.00% (\$\$)	0.00	854.04
Total Parts (\$\$)	14,406.00	7,996.36

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	GLASS FIXING	New	120.00	120.00
2	INTERIOR UPHOLSTERY	New	60.00	60.00
3	DISMANTLE & REPLACE REVERSE SENSOR	New	60.00	30.00
4	CHECK WIRING	New	60.00	20.00
5	SPRAY ANTI RUST PROOF	New	60.00	60.00
6	PANEL BEATING & INSTALL PARTS	New	800.00	680.00
7	PUTTY & SPRAY PAINTING	New	1,000.00	900.00
Gross Labour Cost (\$\$)			2,160.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >