

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24110407/UPA3Q2
Date: 17/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_05
Claimant Vehicle No : GBE3882B Insured Vehicle No : GBM2176X
Date of Loss: 18/11/2024 Nature of Claim: TP Claim No: MFL2024D0013691

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBE3882B
Make & Model: TOYOTA HIACE, 3.0 D DX (M) Engine No: 1KD2556307
Reg. Date: 16/11/2015 (Man. Year: 2015) Chassis No: KDH2010178162
Colour: White Odometer: 369206 km
Engine Capacity: 2982 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15 Rear Tyre Size: 195 R15
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,487.57	3,745.42	742.15	16.54
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,070.00	1,260.00	810.00	39.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,557.57	5,005.42	1,552.15	23.67
Approved Total (Overridden) (S\$)		4,000.00		
Nett Amount (S\$)	6,557.57	4,000.00	2,557.57	39.00
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		27.25		
Nett Liability (S\$)		4,227.25		

INSPECTION

Date of Assignment: 04/12/2024
Date Inspected: 04/12/2024 Inspected At: Quan De Motor Trading
Singapore 417883
Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 20 Feb 2025)	
Parts:	N/A	TOYOTA HIACE 3.0 D DX (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBE3882B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Badly Dented	2,159.20 FL	*2,159.20 FL
2	1		*TAILGATE INNER LOCK	Twisted / Jammed	425.10 FL	*425.10 FL
3	1		*TAILGATE INNER LOCK COVER	Twisted	182.50 FL	*182.50 FL
4	1		*TAILGATE OUTER GARNISH	Cut / Grazed	366.50 FL	*366.50 FL
5	1		*TAILGATE REAR LOGO	Necessary	85.10 FL	*85.10 FL
6	1		*TAILGATE INNER TRIM BOARD	Torn	341.20 FL	*341.20 FL
7	1		*REAR BUMPER	Deformed / Torn	681.20 FL	*681.20 FL
8	1		*REAR BUMPER STEP BRACKET	Bent	233.90 FL	*233.90 FL
9	2		*REAR BUMPER BRACKETS	Repair	130.00 FL	*- FL
10	1		*REAR END PANEL OUTER	Repair	566.20 FL	*- FL
11	1		*TAILLAMP LH	Cracked	399.20 FL	*399.20 FL
12	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*40.00 FS
13	1		*SET REAR BUMPER REVERSE SENSOR	Serviceable	200.00 FS	*- FS
14	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
15	1		*TAILGATE 70KM/H STICKER	Necessary	10.00 FS	*10.00 FS
					Sub Total (\$\$)	5,880.10 4,963.90
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,392.53 1,218.48
					Total Parts (\$\$)	4,487.57 3,745.42

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	20.00
2	TO REMOVE & REFIX REVERSE SENSOR	New	100.00	30.00
3	TO REMOVE & REFIX REAR WINDSCREEN	New	140.00	120.00
4	TO REMOVE & REFIX TAILGATE MECHANISM	New	100.00	60.00
5	TO SPRAY RUST PROOFING	New	80.00	30.00
6	LABOUR FOR PANEL BEATING WELDING & RENEW PARTS	New	800.00	400.00
7	SPRAY PAINTING	New	800.00	600.00
Gross Labour Cost (\$\$)			2,070.00	1,260.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >