



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: AZHARI AFIDI

Ref: CS/INC24110409/Anh3m4(N)

Date: 21/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMX 7014J	Veh. Inspected	SKU 3472K
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1304653-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	19/11/2024

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ A180	c.c	1595
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD1760422J385007	Colour	WHITE
Odometer	132820 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/45R17	PIRELLI	6 mm
L/H Front Tyre	225/45R17	PIRELLI	6 mm
R/H Rear Tyre	225/45R17	PIRELLI	6 mm
L/H Rear Tyre	225/45R17	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/11/2024	Inspect Date / Time	20/11/2024 (02:19 PM)
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **2 Working Days**