

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EGI24060285/UNH3M4**Date:** 17/07/2024REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SNJ7491B**Insured Vehicle No :** XE5949U

Date of Loss: 24/06/2024

Nature of Claim:

TP

Claim No: CDMCG24001556

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SNJ7491B**

Make & Model: HONDA VEZEL, 1.5 G CVT (A)

Engine No: L15Z1008111

Reg. Date: 22/02/2023 (Man. Year: 2022)

Chassis No: RV31006940

Colour: Grey

Odometer: 24789 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16

Rear Tyre Size:

215/60R16

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,035.12	5,954.00	11,081.12	65.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,180.00	2,830.00	1,350.00	32.30
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,215.12	8,784.00	12,431.12	58.60
Approved Total (Overridden) (S\$)		7,000.00		
(S\$)	21,215.12	7,000.00	14,215.12	67.00
+ GST 9.00/9.00% (S\$)	1,909.36	630.00	1,279.36	67.00
Nett Amount (S\$)	23,124.48	7,630.00	15,494.48	67.00

INSPECTION

Date of Assignment: 27/06/2024

Date Inspected: 27/06/2024 Inspected At:

FASTECH AUTO PTE LTD

1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY
SINGAPORE 417883

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jul 2024)
Parts:	144	HONDA VEZEL 1.5 G CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNJ7491B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Not Necessary	110.20 FL	*- FL
2	1		*TAILGATE	Repair	1,499.20 FL	*- FL
3	1		*TAILGATE OUTER PANLE COVER	Repair	980.20 FL	*- FL
4	1		*TAILGATE VEZEL EMBLEM	Not Necessary	66.80 FL	*- FL
5	1		*TAILGATE REFLECTOR O/S	Serviceable	700.00 FL	*- FL
6	1		*TAILGATE INNER LOCK	Not Necessary	199.80 FL	*- FL
7	1		*TAILGATE LOCK STRIKER	Not Necessary	66.00 FL	*- FL
8	1		*TAILGATE INNER TRIM BOARD	Not Necessary	435.00 FL	*- FL
9	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	50.00 FL	*- FL
10	1		*TAILGATE WEATHERSTRIP	Not Necessary	288.00 FL	*- FL
11	1		*REAR BUMPER TOP	Distorted	980.00 FL	*892.00 FL
12	1		*REAR BUMPER CENTRE	Distorted	870.20 FL	*650.00 FL
13	1		*REAR BUMPER UNDER COVER	Not Necessary	541.00 FL	*- FL
14	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*50.00 FL
15	1		*REAR BUMPER REFLECTOR O/S	Cracked	65.00 FL	*65.00 FL
16	1		*SET REAR BUMPER CLIPS	Repeated	50.00 FL	*- FL
17	1		*REAR BUMPER SIDE RETAINER O/S	Cracked	45.00 FL	*45.00 FL
18	1		*REAR END PANEL	Dented/Bent	665.20 FL	*547.00 FL
19	1		*REAR END PANEL TOP GARNISH	Serviceable	341.10 FL	*- FL
20	1		*TAILLAMP O/S	Scratched	900.00 FL	*681.20 FL
21	1		*TAILLAMP HOUSING PANEL O/S	Dented	700.00 FL	*520.50 FL
22	1		*REAR BUZZLE SENSOR	Not Necessary	98.00 FL	*- FL
23	1		*REAR FENDER O/S	Dented/Warped	1,483.00 FL	*1,193.20 FL
24	1		*REAR FENDER OUTER PROTECTOR O/S	Torn	760.00 FL	*380.20 FL
25	1		*REAR FENDER INNER TRIM BOARD O/S	Distorted	790.00 FL	*421.20 FL
26	1		*REAR FENDER UNDER INNER CLOTH O/S	Torn	388.20 FL	*293.50 FL
27	1		*REAR FLOOR PANEL	Repair	1,280.00 FL	*- FL
28	1		*REAR FLOOR INNER SIDE PANEL O/S	Bent/Twisted	450.00 FL	*450.00 FL
29	1		*REAR FLOOR PANEL TOOLS SPONGE	Torm	522.00 FL	*441.20 FL
30	1		*REAR EXHAUST	Not Necessary	765.00 FL	*- FL
31	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	108.00 FL	*- FL
32	1		*REAR WHEEL HUB BEARING O/S	Serviceable	485.00 FL	*- FL
33	1		*REAR AXLE BEAM ASSY	Not Necessary	1,899.00 FL	*- FL
34	1		*REAR SHOCK ABSORBER O/S	Not Necessary	288.00 FL	*- FL
35	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
36	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	50.00 FS	*- FS
37	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
38	1		*SET REAR BUMPER REVERSE SENSOR	Serviceable	680.00 FS	*- FS
39	1		*REAR SPORT RIM O/S	Cut	950.00 FS	*600.00 FS
40	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	20,818.90	7,280.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,783.78	1,326.00
Total Parts (\$\$)	17,035.12	5,954.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REVERSE SENSOR	New	80.00	30.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	0.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
6	TO RESET & REPROGRAMME DIAGNOSIS SYSTEM	New	180.00	60.00
7	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
8	TO SPRAY RUST PROOFING	New	100.00	80.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	1,800.00	1,400.00
10	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,150.00
Gross Labour Cost (\$\$)			4,180.00	2,830.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >