



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNM 6387K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER LOWER LIP	CUT/TORN	\$1,221.40	\$1,221.40
1	FRONT BUMPER	CUT/TORN	\$940.50	\$726.00
1	FRONT BUMPER SIDE RETAINERS	SERVICEABLE	\$60.30	\$0.00
1	FRONT HEADLAMPS	NOT NECESSARY	\$1,784.50	\$0.00
1	FRONT FENDER (L)	TO REPAIR SEE LABOUR	\$680.40	\$0.00
1	FRONT FENDER INNER SHIELD (L)	NOT NECESSARY	\$155.20	\$0.00
1	FRONT FENDER WHEEL ARCH GARNISH (L)	CUT	\$488.30	\$315.00
1	FRONT WHEEL RIM	TO REPAIR SEE LABOUR	\$1,350.40	\$0.00
1	FRONT WHEEL BEARINGS	NOT NECESSARY	\$363.00	\$0.00
1	FRONT KNUCKLE ARMS	NOT NECESSARY	\$589.70	\$0.00
	<b>LESS 10.00% DISCOUNT</b>		(\$763.37)	(\$226.24)
			<b>\$6,870.33</b>	<b>\$2,036.16</b>
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$60.00	\$30.00
1	SET FRONT FENDER INNER SHIELD CLIP (SN)	NOT NECESSARY	\$60.00	\$0.00
1	FRONT TYRE (SN)	SERVICEABLE	\$300.00	\$0.00
			<b>\$420.00</b>	<b>\$30.00</b>
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REFIT FRONT UNDERCARRIAGE	NOT NECESSARY	\$500.00	\$0.00
	TO CONDUCT WHEEL ALIGNMENT	NOT NECESSARY	\$180.00	\$0.00
	TO APPLY UNDERCOATING	NOT NECESSARY	\$120.00	\$0.00
	PANEL BEATING. INCLUSIVE OF THE REPAIR OF FRONT FENDER (L) AND FRONT WHEEL RIM		\$1,000.00	\$300.00
	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS		\$1,200.00	\$580.00
			<b>\$3,000.00</b>	<b>\$880.00</b>
<b>GRAND TOTAL</b>			<b>\$10,290.33</b>	<b>\$2,946.16</b>



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>		<b>\$2,300.00</b>
<b>Report Ref No: CS/INC24110411/Uqh3m4</b>			

**TOTAL FOR SPARE PARTS: \$ 7,290.33 \$ 2,066.16**  
**TOTAL FOR LABOUR : \$ 3,000.00 \$ 880.00**  
**TOTAL REPAIR COST: \$10,290.33 \$ 2,946.16**

## CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.