

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 2622G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOTLID	BENT	2,430.00	2,430.00
1	REAR BOOTLID LOCK	DENTED	289.00	289.00
1	REAR BOOTLID EMBLEM	NECESSARY	120.00	120.00
1	REAR BOOTLID EMBLEM(BRZ)	NECESSARY	90.00	90.00
1	REAR LAMP	BROKEN	460.00	460.00
1	REAR FENDER	BENT	1,490.00	1,490.00
1	REAR BOOTLID LAMP BRACKET	CRACKED	45.00	45.00
1	REAR BUMPER RETAINER	CRACKED	60.00	60.00
1	REAR TAIL LAMP PANEL	BENT	380.00	380.00
1	REAR BUMPER REFORCEMENT	BENT	310.00	310.00
1	REAR PANEL	BENT	580.00	580.00
1	REAR WINDSCREEN RUBBER	NECESSARY	211.00	211.00
1	REAR FUEL CAP	SERVICEABLE	180.00	-
1	REAR BUMPER	BENT	920.00	920.00
1	REAR BUMPER LOWER LID	CRACKED	790.00	790.00
	LESS 10% DISCOUNT		-835.50	-
	LESS 20% DISCOUNT		-	-1,635.00
			7,519.50	6,540.00
1	REAR BOOTLID RUBBER (50%) (SN)	DISTORTED/ DENTED	260.00	130.00
	LESS 10% DISCOUNT		-26.00	-
			234.00	130.00
	SPECIAL NETT ITEMS			
1	REVERSE SENSOR (SN)	DENTED	250.00	200.00
	, ,		250.00	200.00
	<u>LABOUR</u>			
	TOWING FEES.		120.00	100.00
	TO RENEW ABOVE PARTS.		1,700.00	1,200.00
	TO RESPRAY JOB.		1,200.00	·

Report Ref No. CS/SMO24110415/Knp3m4(N)



RECOMMENDED COST OF REPAIRS

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

9,520.00

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	ANTI RUST.		30.00	30.00
	TO REMOVE REAR WINDSCREEN AND QUARTER GLASS.		250.00	180.00
	TO CHECK WIRING.		30.00	20.00
	TO REMOVE UPHOLSTERY.		120.00	120.00
			3,450.00	2,650.00
	GRAND TOTAL		11,453.50	9,520.00

Report Ref No. CS/SMO24110415/Knp3m4(N)

KONG SENG CHEONG

Licensed Appraiser