



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLV 4034T

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRY (SN)	NECESSARY	\$100.00	\$50.00
1	COVER, RR BUMPER (SN)	CRUSHED	\$2,298.00	\$543.90
1	GUARD, RR BUMPER, (SN)	BROKEN	\$573.60	\$573.60
1	PLATE, RR BUMPER, (SN)	NOT NECESSARY	\$24.60	\$0.00
6	RETAINER, OUTSIDE (SN)	NECESSARY	\$33.60	\$33.60
1	REINFORCEMENT (SN)	BENT	\$512.40	\$512.40
1	RETAINER, RR BUMPER (SN)	NOT NECESSARY	\$155.60	\$0.00
1	RETAINER, RR BUMPER, (SN)	NOT NECESSARY	\$78.90	\$0.00
1	PLATE, RR BUMPER, LH (SN)	NOT NECESSARY	\$126.10	\$0.00
1	REFLECTOR ASSY, (SN)	NOT NECESSARY	\$83.40	\$0.00
10	PIECE, RR BUMPER (SN)	NECESSARY	\$58.00	\$58.00
1	BRACKET, FOG LAMP (SN)	NOT NECESSARY	\$110.60	\$0.00
1	PANEL SUB-ASSY, BODY (SN)	TO REPAIR SEE LABOUR	\$1,092.40	\$0.00
1	COVER, FLOOR UNDER (SN)	NOT NECESSARY	\$262.10	\$0.00
1	INSULATOR, MAIN (SN)	NOT NECESSARY	\$201.00	\$0.00
1	COVER, DECK TRIM, RR (SN)	NOT NECESSARY	\$352.20	\$0.00
2	RETAINER, ULTRASONIC (SN)	NECESSARY	\$43.00	\$43.00
1	PAD, RR BUMPER, RH (SN)	NOT NECESSARY	\$18.20	\$0.00
2	RETAINER, ULTRASONIC (SN)	NECESSARY	\$56.60	\$56.60
1	SENSOR, ULTRASONIC, (SN)	CUT	\$503.90	\$503.90
1	PIPE ASSY, EXHAUST (SN)	BENT	\$2,624.80	\$2,624.80
			\$9,309.00	\$4,999.80

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	DRILL HOLE AND INSTALL REVERSE SENSOR		\$198.00	\$198.00
	CHECK WIRING SYSTEM		\$134.64	\$134.64
	REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR		\$792.00	\$0.00
	TO RESET ECU AND REPROGRAMME		\$198.00	\$198.00
	TO CONDUCT ADJUSTMENT ON BLIND SPOT SENSOR		\$198.00	\$198.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REPLACE REAR EXHAUST PIPE SYSTEM		\$792.00	\$792.00
	REPLACE ACC DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY, BODY		\$3,960.00	\$1,584.00
	RESPRAY ACC AFFECTED AREAS		\$3,280.00	\$1,312.00
			\$9,552.64	\$4,416.64
GRAND TOTAL			\$18,861.64	\$9,416.44
	RECOMMENDED COST OF REPAIRS			\$9,416.44
Report Ref No: CS/FCI24110418/Enp3m4				

MARKET VALUE: \$50,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$21,257.00=NETT VALUE: \$28,743.00

**CTY**

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.