

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/ICS24110419/UNP3E2
Date: 12/12/2024REFERENCE

Handling Insurer:	ECICS Limited	Policy No:	
Claimant Vehicle No :	SLS8533J	Insured Vehicle No :	GBK9369X
Date of Loss:	18/11/2024	Nature of Claim:	TP
		Claim No:	DMCV2400256H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS8533J	Engine No:	PE10525207
Make & Model:	MAZDA 5 WAGON, 2.0 (A)	Chassis No:	JM6CW1071H0126500
Reg. Date:	09/10/2017 (Man. Year: 2017)	Odometer:	119205 km
Colour:	Blue		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,416.30	4,816.90	1,599.40	24.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,910.00	2,450.00	1,460.00	37.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,326.30	7,266.90	3,059.40	29.63
Approved Total (Overridden) (S\$)		5,800.00		
(S\$)	10,326.30	5,800.00	4,526.30	43.83
+ GST 9.00/9.00% (S\$)	929.37	522.00	407.37	43.83
Nett Amount (S\$)	11,255.67	6,322.00	4,933.67	43.83

INSPECTION

Date of Assignment:	19/11/2024	
Date Inspected:	20/11/2024	Inspected At: Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	6.0 days	

Adjuster: MARCUS CHUA**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 12 Dec 2024)	
Parts:	N/A	MAZDA 5 WAGON 2.0 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLS8533J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER (WCP)	Cut / Deformed	380.00 F	*380.00 F
2	1		*FRONT BUMPER SIDE RETAINER - LH (WCP)	Cracked	18.00 F	*18.00 F
3	10		*FRONT BUMPER CLIPS (WCP)	Necessary	28.00 F	*28.00 F
4	1		*FRONT BUMPER FOGLAMP COVER - LH (WCP)	Not Necessary	35.00 F	*- F
5	1		*HEADLAMP UNIT - LH (WCP)	Cracked	650.00 F	*650.00 F
6	1		*HEADLAMP LOWER RETAINER - LH (WCP)	Not Necessary	20.00 F	*- F
7	1		*FRONT FENDER - LH (WCP)	Dented / Bent	150.00 F	*150.00 F
8	1		*FRONT FENDER COWLING - LH (WCP)	Torn	95.00 F	*95.00 F
9	10		*FRONT FENDER COWLING CLIPS - LH (WCP)	Necessary	28.00 F	*28.00 F
10	1		*FRONT RIM - LH (WCP)	Cut	550.00 F	*550.00 F
11	1		*FRONT DOOR - LH (WCP)	Dented / Bent	650.00 F	*650.00 F
12	1		*FRONT DOOR STICKER - LH (WCP)	Necessary	110.00 F	*110.00 F
13	1		*FRONT DOOR WEATHERSTRIP - LH (WCP)	Not Necessary	38.00 F	*- F
14	1		*FRONT DOOR TOP HINGE - LH (WCP)	Serviceable	25.00 F	*- F
15	1		*FRONT DOOR LOWER HINGE - LH (WCP)	Serviceable	20.00 F	*- F
16	1		*FRONT DOOR CHECKER - LH (WCP)	Serviceable	40.00 F	*- F
17	1		*FRONT DOOR OUTER CHANNEL MOULDING - LH (WCP)	Grazed	65.00 F	*65.00 F
18	1		*FRONT DOOR GLASS - LH (WCP)	Cut	150.00 F	*150.00 F
19	1		*SIDE MIRROR ASSY - LH (WCP)	Cracked	150.00 F	*150.00 F
20	1		*SIDE MIRROR OUT COVER - LH (WCP)	Missing	55.00 F	*55.00 F
21	1		*REAR DOOR - LH (WCP)	Repair	580.00 F	*- F
22	1		*REAR DOOR STICKER - LH (WCP)	Not Necessary	110.00 F	*- F
23	1		*REAR DOOR WEATHERSTRIP - LH (WCP)	Not Necessary	85.00 F	*- F
24	1		*ROCKER PANEL OUTER GARNISH - LH (WCP)	Repair	455.00 F	*- F
25	1		*REAR FENDER - LH (WCP)	Dented / Bent	850.00 F	*850.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*REAR BUMPER - LH (WCP)	Cut / Torn	450.00 F	*450.00 F
27	1		*REAR BUMPER SIDE RETAINER - LH (WCP)	Not Necessary	18.00 F	*- F
28	10		*REAR BUMPER CLIPS (WCP)	Not Necessary	28.00 F	*- F

F=Franchise part.

Sub Total (\$)	5,833.00	4,379.00
+ Margin on L,N Items 10.00/10.00% (\$)	583.30	437.90
Total Parts (\$)	6,416.30	4,816.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO KNOCK OUT DENTS, CUT / WELD REAR FENDER, REMOVE, REPLACE ACCIDENT PORTIONS	New	1,760.00	990.00
2	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,600.00	1,200.00
3	TO CHECK WIRING	New	30.00	30.00
4	TO REMOVE, REFIT GARNISH TO FACILITATE REPAIR	New	150.00	60.00
5	ANTI RUST	New	90.00	50.00
6	TO TRANSFER 2 DOOR FITTINGS	New	160.00	60.00
7	TO 4 WHEEL ALIGNMENT	New	75.00	60.00
8	TO REMOVE, REPLACE RIM & TYRE BALANCING	New	45.00	0.00
Gross Labour Cost (S\$)			3,910.00	2,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >