



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKT 8910K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BOOT	BENT	\$965.50	\$965.50
1	REAR BOOT LOGO	NECESSARY	\$64.30	\$64.30
1	REAR BOOT EMBLEM "CITY"	NECESSARY	\$71.20	\$71.20
1	REAR BOOT MOULDING	SCRATCHED	\$155.20	\$155.20
1	REAR BOOT LOCK	SERVICEABLE	\$160.10	\$0.00
1	REAR BOOT RUBBER	NECESSARY	\$117.60	\$117.60
1	REAR BOOT LAMP RH	CRACKED	\$279.50	\$279.50
1	REAR PANEL	BENT	\$476.40	\$476.40
1	REAR PANEL TRIM	SERVICEABLE	\$112.30	\$0.00
1	REAR LAMP RH	CRACKED	\$395.20	\$395.20
1	REAR BUMPER	DEFORMED	\$786.40	\$786.40
2	REAR BUMPER BRACKET L+R @\$55.20	O/S NECESSARY	\$110.40	\$55.20
10	REAR BUMPER CLIPS @\$3.90	NECESSARY	\$39.00	\$39.00
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	\$96.30	\$0.00
2	REAR BUMPER SENSOR @\$296.70	SCRATCHED (1PCS ONLY)	\$593.40	\$296.70
	<b>LESS 20.00% DISCOUNT</b>		(\$884.56)	(\$740.44)
			<b>\$3,538.24</b>	<b>\$2,961.76</b>

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR NUMBER PLATE (SN)	CRACKED	\$45.00	\$35.00
			<b>\$45.00</b>	<b>\$35.00</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CUT & WELD REAR END PANEL, TO REPAIR REAR LAMP PANEL, REAR SPARE TYRE PANEL, TO REMOVE & REFIX DAMAGED PARTS STRAIGHTEN & REALIGN AFFECTED AREAS		\$840.00	\$300.00
	TO SPRAY AFFECTED AREAS, REAR BOOT, REAR END PANEL, REAR FENDER L+R, SPARE TYRE PANEL, REAR BUMPER, REAR REVERSE SENSOR, AND AFFECTED AREAS		\$850.00	\$200.00
	TO REMOVE & REFIX LUGGAGE COMPARTMENT SIDE GARNISH SIDE TRIMBOARD & OTHER ATTACHMENT PARTS		\$80.00	\$40.00
	TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE		\$60.00	\$40.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO RUST PROOF AFFECTED AREAS		\$50.00	\$30.00
			\$1,880.00	\$610.00
GRAND TOTAL			\$5,463.24	\$3,606.76
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,700.00
Report Ref No: CS/AWA24060286/Rv h3e2				

**MRB**

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.