

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
IED WORLD AS	SURANCE COMPANY LTD	Ref:	CS/AWA24060286/Rvh3e2
(SINGAPORE BRANCH)		Date:	09/09/2024
		Code:	AWA
1. Policy Particulars :- THIRD PARTY CLAIM			
ured Veh.	XD 6783D	Veh. Inspected	SKT 8910K
icy No.	BVFCSB0014402300	Coverage	0
im No.	NSV2400169/PC	Excess	\$0.00
sign From	HEW LEE FONG	Assign Date	27/06/2024
2. Vehicle Details			
ke & Model	HONDA CITY 1.5 SV CVT	c.c	1497
gine No.	L15Z12704274	Year of Reg.	25/06/2015
assis No.	MRHGM6660GP000108	Colour	GREY
ometer	419934 KM	Steering	IN ORDER
kes	IN ORDER	General	GOOD
dification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres			
	a :	Make	Balance (mm)
	Size	Wake	Balarioo (iiiiii)
l Front Tyre	185/55 R16	KAPSEN	6
Front Tyre			, ,
	185/55 R16	KAPSEN	6
Front Tyre	185/55 R16 185/55 R16	KAPSEN KAPSEN	6
Front Tyre Rear Tyre	185/55 R16 185/55 R16 185/55 R16	KAPSEN KAPSEN KAPSEN KAPSEN	6 6 6
Front Tyre Rear Tyre Rear Tyre	185/55 R16 185/55 R16 185/55 R16 185/55 R16	KAPSEN KAPSEN KAPSEN KAPSEN Of Damages	6 6 6
Front Tyre Rear Tyre Rear Tyre	185/55 R16 185/55 R16 185/55 R16 185/55 R16 Description o ED DAMAGES AT THE REAR PORTION	KAPSEN KAPSEN KAPSEN KAPSEN Of Damages	6 6 6
Front Tyre Rear Tyre Rear Tyre	185/55 R16 185/55 R16 185/55 R16 185/55 R16 Description o ED DAMAGES AT THE REAR PORTION	KAPSEN KAPSEN KAPSEN KAPSEN Of Damages	6 6 6
Front Tyre Rear Tyre Rear Tyre	185/55 R16 185/55 R16 185/55 R16 185/55 R16 185/55 R16 Description of ED DAMAGES AT THE REAR PORTION 6.	KAPSEN KAPSEN KAPSEN KAPSEN Of Damages	6 6 6
Front Tyre I Rear Tyre Rear Tyre HICLE SUSTAINE	185/55 R16 185/55 R16 185/55 R16 185/55 R16 185/55 R16 Description of the Description of	KAPSEN KAPSEN KAPSEN KAPSEN OF Damages N. Formation Inspection Date	6 6 6 6
Front Tyre Rear Tyre HICLE SUSTAINE ES SEE DETAILS	185/55 R16 185/55 R16 185/55 R16 185/55 R16 Description of the second o	KAPSEN KAPSEN KAPSEN KAPSEN Of Damages N. Formation Inspection Date	6 6 6 6
Front Tyre Rear Tyre HICLE SUSTAINE ES SEE DETAILS Cident Date Evey held at	185/55 R16 185/55 R16 185/55 R16 185/55 R16 Description of the second o	KAPSEN KAPSEN KAPSEN KAPSEN TO DAMAGES N. Formation Inspection Date -04/06/08 . Arks JUDICE" BASIS.	6 6 6 6
	IGAPORE BRAN INSON ROAD #0 PLETREE ANSO Ired Veh. cy No. m No. ign From Ge & Model ine No. ssis No.	IED WORLD ASSURANCE COMPANY LTD IGAPORE BRANCH) INSON ROAD #08-01 (8TH FLOOR) PLETREE ANSON SINGAPORE 079914 Policy Particulars :- T Ired Veh. XD 6783D Cy No. BVFCSB0014402300 m No. NSV2400169/PC ign From HEW LEE FONG Vehicle In the No. L15Z12704274 ssis No. MRHGM6660GP000108 ometer 419934 KM kes IN ORDER Iffication(s) RIMS: SPORTS RIM	IED WORLD ASSURANCE COMPANY LTD IGAPORE BRANCH) INSON ROAD #08-01 (8TH FLOOR) PLETREE ANSON SINGAPORE 079914 Policy Particulars: - THIRD PARTY CLAI Ired Veh. XD 6783D IVeh. Inspected Cy No. BVFCSB0014402300 Coverage IM No. NSV2400169/PC IGH FROM INSUME TO BE TO

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days