



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMW 1625R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR SLIDING DOOR RH	DENTED	1,588.60	1,588.60
1	REAR SLIDING DOOR OUTER GARNISH	DEFORMED	320.00	320.00
1	REAR FENDER RH	TO REPAIR SEE LABOUR	1,120.50	-
1	REAR FENDER OUTER GARNISH	CUT	160.00	160.00
	LESS 25% DISCOUNT		-797.28	-517.15
			2,391.82	1,551.45
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR DOOR OUTER GARNISH CLIPS (SN)	NECESSARY	20.00	20.00
1	SET REAR FENDER OUTER GARNISH CLIPS (SN)	NECESSARY	20.00	10.00
			40.00	30.00
	<u>LABOUR</u>			
	PANEL BEATING, REMOVAL AND REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER RH.		1,200.00	300.00
	TO SPRAY PAINT AFFECTED AREA.		1,200.00	400.00
	TUFF COAT.		200.00	30.00
	WIRING CHECK.	NOT NECESSARY	100.00	-
	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR.	NOT NECESSARY	280.00	-
	REMOVE AND REFIX REAR DOOR MECHANISM.		120.00	60.00
			3,100.00	790.00
	GRAND TOTAL		5,531.82	2,371.45
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,900.00

Report Ref No. CS/FCI24110429/Aqp3m4(N)

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.