



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD 16 RAFFLES QUAY #42-01 HONG LEONG BUILDINGSINGAPORE 048581 ATTN: CHRIS LIM		Ref: CS/FCI24110429/Aqp3m4(N) Date: 27/01/2025 Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SHC 3381U	Veh. Inspected	SMW 1625R
Policy No.	D-24101861MFCT	Coverage (\$)	0.00
Claim No.	D24010134MFCT	Excess (\$)	0.00
Assign From	SWEE KEONG	Assign Date	20/11/2024
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA SIENTA HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2020
Chassis No.	NHP1707194650	Colour	BROWN
Odometer	246766 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	185/60R15	KING BOSS	6 mm
L/H Front Tyre	185/60R15	KING BOSS	6 mm
R/H Rear Tyre	185/60R15	KING BOSS	6 mm
L/H Rear Tyre	185/60R15	KING BOSS	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	17/11/2024	Inspection Date	25/11/2024
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
<b>5a. Remarks</b>			
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	