



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24110431/Kvp3e2
16 RAFFLES QUAY	Date:	11/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 7758B	Veh. Inspected	SNG 9758K
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24010111MFCT	Excess	\$0.00
Assign From	JOANNE	Assign Date	20/11/2024

2. Vehicle Details

Make & Model	HONDA SHUTTLE (A)	C.C	1496
Engine No.	LEB7609294	Year of Reg.	20/09/2022
Chassis No.	GP72207586	Colour	METALLIC GREY
Odometer	218961 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	185/60R15	ANNAITE	7
L/H Front Tyre	185/60R15	ANNAITE	7
R/H Rear Tyre	185/60R15	ANNAITE	7
L/H Rear Tyre	185/60R15	ANNAITE	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	16/11/2024	Inspection Date	02/12/2024
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days